





report date: 2024-03-28

General information

Make	PEUGEOT
Model	108 ACTIVE
Colour	Purple
Year of manufacture	2018
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	95 Nm at 4.300 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	56.5 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	95 g/km
CO2 label	А



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-05-24

Pictures 21

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/11



SB67GYU report date: 2024-03-28

MOT history

MOT expiry date	2024-06-28
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	14
Total items failed	0

MOT #5		2023-06-29 10:38
MOT test	number	197073446403
Result		✓ Passed
Next expi	ry date	2024-06-28
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice (a) (i))	Offside Front Anti-roll bar linkage pin or bush worn but not resulting in exce	essive movement (5.3.4
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice (5.3.4 (a) (Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in ex	ccessive movement
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #4		2022-06-29 10:54
MOT test	number	488241314766
Result		✓ Passed
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords ((5.2.3 (d) (i))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords ((5.2.3 (d) (i))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #3

MOT test number

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

 MOT #2
 2020-12-15 09:03

 MOT test number
 251132696256

 Result
 ✓ Passed

 MOT #1
 2020-12-14 15:23

 MOT test number
 429524099202

 Result
 X Failed

MAJOR Offside Rear Service brake excessively binding (1.2.1 (f))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	28 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
First licence fee (12 months)	£ 165,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



SB67GYU report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Plate since

SB67GYU

report date: 2024-03-28

UK UK

More info >

Owner history		
For how long did the current and previous owner(s) have this PEUGEOT? How many owne have? Check it in the premium report and see all owner registrations. Download the full re		JGEOT

HEREE STATE OF THE		

THE STREET STREET		
	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		n.n.n

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

Contact info

More info >

CarCheck.co.uk page 9/11



SB67GYU report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-01-25
Last registration	2023-06-29
Complete history	See info



Registration #1	2018-01-25	28 mi
Registration #2	2020-12-14	4.963 mi
Registration #3	2020-12-15	4.965 mi
Registration #4		77,777 66
Registration #5		9.39 es
Registration #6		71.777 66
Registration #7		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1615 mm
Height	1460 mm
Length	3475 mm
Wheel base	2340 mm
Kerb weight	840 kg
Max. allowed weight	1240 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	8378370

CarCheck.co.uk page 11/11