



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VVTI COLOUR COLLECTION
Colour	Blue
Year of manufacture	2006
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	129 Nm at 4.400 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-14
Pictures	34
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-15
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	17
Total items failed	15

MOT #17 2023-10-16 15:29

MOT test number 359743573772

Result ✓ Passed

Next expiry date 2024-10-15

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

MOT #16 2023-10-13 14:37

MOT test number 834964155377

Result ✗ Failed

- Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))



MOT #15	2022-07-11 14:06
MOT test number	512049991608
Result	✓ Passed
Advice	Nearside Rear hand brake reading low

MOT #14	2022-07-08 15:40
MOT test number	285560474045
Result	✗ Failed
Fail	Front Headlamp lens seriously defective both sides (4.1.1 (b) (ii))
Fail	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Front Headlamp aim projected beam image is obviously incorrect both sides (4.1.2 (c))
Fail	Offside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear hand brake reading low

MOT #13	2021-07-12 11:11
MOT test number	915532245468
Result	✓ Passed

MOT #12	2021-07-12 11:11
MOT test number	538902080050
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))

MOT #11	2020-06-11 09:03
MOT test number	896002401716
Result	✓ Passed
Advice	Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #10** 2019-06-12 10:49**MOT test number** 367065080764**Result** ✓ Passed**MOT #9** 2018-06-25 13:46**MOT test number** 565370181080**Result** ✓ Passed**MOT #8** 2016-08-20 07:28**MOT test number** 252974416644**Result** ✓ Passed**MOT #7** 2016-08-09 09:03**MOT test number** 992166457887**Result** ✗ Failed

- Fail** Front front brake application uneven (3.7.B.2)
- Fail** Brake pedal creeps down when held under pressure (3.3.B.1a)
- Fail** Offside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Fail** Nearside Front front brake excessively fluctuating (3.7.B.3)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)
- Fail** Offside Front Lower Suspension arm corroded and seriously weakened (2.4.G.1)
- Fail** Front Brakes imbalanced across an axle 42% (3.7.B.5b)

MOT #6 2015-08-17 11:39**MOT test number** 202166554047**Result** ✓ Passed

**MOT #5** 2014-08-23 13:55**MOT test number** 717955934257**Result** ✓ Passed**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Nearside rear tyre sidewall starting to crack**MOT #4** 2013-08-12 15:21**MOT test number** 236144023276**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2012-08-25 09:05**MOT test number** 539298732235**Result** ✓ Passed**MOT #2** 2011-09-01 08:58**MOT test number** 688964841273**Result** ✓ Passed**Advice** Offside front brake juddering slightly (3.7.A.2b)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2009-09-09 13:14**MOT test number** 602372659208**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
15 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	15 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-16
Last registration	2023-10-16
Complete history	See info



Registration #1	2006-09-16	20 mi
Registration #2	2009-09-09	36.102 mi
Registration #3	2011-09-01	53.501 mi
Registration #4	2012-08-25	62.684 mi
Registration #5	2013-08-12	75.924 mi
Registration #6	2014-08-23	87.428 mi
Registration #7	2015-08-17	97.051 mi
Registration #8	2016-08-09	108.327 mi
Registration #9	2016-08-20	108.753 mi
Registration #10	2018-06-25	111.950 mi
Registration #11	2019-06-25	115.277 mi
Registration #12	2019-06-25	115.277 mi
Registration #13	2019-06-25	115.277 mi
Registration #14	2019-06-25	115.277 mi
Registration #15	2019-06-25	115.277 mi
Registration #16	2019-06-25	115.277 mi
Registration #17	2019-06-25	115.277 mi
Registration #18	2019-06-25	115.277 mi
Registration #19	2019-06-25	115.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1710 mm
Height	1475 mm
Length	4180 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1655 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4ZZU798028