





General information

| Make | AUDI |
|---------------------|------------------------|
| Model | A3 T FSI S LINE |
| Colour | Black |
| Year of manufacture | 2007 |
| Top speed | 147 mph |
| 0 - 60 mph | 6.9 seconds |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| Power | 200 BHP |
|-------------------------|---------------------|
| Max. torque | 279 Nm at 1.800 rpm |
| Engine capacity | 1.984 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 26.7 mpg |
| Consumption extra urban | 47.1 mpg |
| Consumption combined | 36.7 mpg |
| CO2 emission | 186 g/km |
| CO2 label | J |





MOT history

| MOT expiry date | 2021-04-02 |
|--------------------|------------|
| MOT pass rate | 73 % |
| MOT passed | 11 |
| Failed MOT tests | 4 |
| Total advice items | 32 |
| Total items failed | 9 |

| MOT #15 | 2020-04-03 09:27 |
|--|------------------------------|
| MOT test number | 731746758219 |
| Result | ✓ Passed |
| Next expiry date | 2021-04-02 |
| Advice Nearside Front Brake disc worn, pitted or scored, but not seriously | / weakened (1.1.14 (a) (ii)) |

| MOT #14 | 2020-04-02 10:23 |
|--|-------------------------|
| MOT test number | 641133530044 |
| Result | 🗙 Failed |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longe of dirt (6.1.7 (g) (ii)) | er prevents the ingress |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |
| Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weaken | ed (1.1.14 (a) (ii)) |
| Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no lon ingress of dirt (6.1.7 (g) (ii)) | ger prevents the |





| MOT #13 | | 2019-03-26 14:32 |
|-----------------------|---|---------------------|
| MOT test | number | 960885621766 |
| Result | | ✓ Passed |
| Advice | Oil level is low | |
| Advice | Front Tyre worn close to legal limit/worn on edge Both front tyres wearing on ec | lges (5.2.3 (e)) |
| Advice | Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) | |
| Advice | Oil warning light on | |
| Minor (g) (i)) | Front Drive shaft joint constant velocity boot severely deteriorated Both front out | ter cv boots (6.1.7 |
| Advice | Front Brake disc worn, but not excessively Both front disks (1.1.14 (a) (i)) | |

| MOT #12 | 2019-03-25 14:50 |
|--|---------------------------|
| MOT test number | 470214263449 |
| Result | 🗙 Failed |
| Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) | |
| Minor (g) (i)) Front Drive shaft joint constant velocity boot severely deteriorated Both from | ont outer cv boots (6.1.7 |
| Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) | |
| Advice Oil warning light on | |
| Advice Front Brake disc worn, but not excessively Both front disks (1.1.14 (a) (i)) | |
| Advice Front Tyre worn close to legal limit/worn on edge Both front tyres wearing | on edges (5.2.3 (e)) |
| Advice Oil level is low | |





2018-03-28 07:57

591076735421

| MOT #11 | | 2018-03-28 11:00 |
|--------------------------|---|---------------------------|
| MOT test i | number | 546207539014 |
| Result | | ✓ Passed |
| Advice (2.5.C.1a) | Offside Outer Front constant velocity joint gaiter deteriorated, but preventi | ng the ingress of dirt |
| Advice | Engine management light is on | |
| Advice (2.5.C.1a) | Nearside Outer Front constant velocity joint gaiter deteriorated, but prever | nting the ingress of dirt |
| Advice | Oil light is on | |

| мот | #10 |
|-----|-----|
| | |

MOT test number

| Result | 🗙 Failed |
|---|-------------|
| Advice Engine management light is on | |
| Fail Nearside Headlamp not working on dipped beam (1.7.5a) | |
| Advice Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingr | ess of dirt |
| (2.5.C.1a) | |
| Advice Oil light is on | |
| Fail Nearside Stop lamp not working (1.2.1b) | |
| Advice Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingres (2.5.C.1a) | s of dirt |
| (2.5.0.14) | |

| MOT #9 | | 2017-03-20 12:05 |
|--------------------------|--|------------------|
| MOT test | number | 479619712068 |
| Result | | ✓ Passed |
| Advice | Engine management light is on | |
| Advice (2.5.C.1a) | Offside Outer Front constant velocity joint gaiter damaged, but preventing the | ingress of dirt |





| MOT #8 | | 2016-03-15 09:35 |
|--------------------------|---|------------------------|
| MOT test | number | 529137082524 |
| Result | | ✓ Passed |
| Advice | Oil warning lamp is on | |
| Advice (2.5.C.1a) | Nearside Outer Front constant velocity joint gaiter deteriorated, but preventir | ng the ingress of dirt |
| Advice | Engine management light is on | |
| | | |
| MOT #7 | | 2015-05-22 16:49 |
| MOT test | number | 706862145199 |
| Result | | ✓ Passed |
| | | |
| MOT #6 | | 2014-05-30 13:38 |
| MOT test | number | 485160454106 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| | | |
| MOT #5 | | 2013-03-28 17:46 |
| MOT test | number | 156187083472 |
| Result | | ✓ Passed |
| MOT #4 | | 2013-03-28 14:30 |
| MOT | | 107627402450 |

| MOT test number | 107637483450 |
|--|--------------|
| Result | 🗙 Failed |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |



Result



🗸 Passed

| MOT #3 | 2012-04-27 15:19 |
|---|----------------------------------|
| MOT test number | 206018312489 |
| Result | ✓ Passed |
| AdviceNearside Front Tyre worn close to the legal limit (4.1.E.1)AdviceOffside Front Tyre worn close to the legal limit (4.1.E.1) | |
| MOT #2 MOT test number | 2011-03-30 12:38 765819781004 |

| MOT #1 | 2010-04-23 11:13 |
|-----------------|------------------|
| MOT test number | 263933210191 |
| Result | ✓ Passed |



RF07KVO report date: 2024-03-29

Tax & MOT check

| X Untaxed Tax expired: 31 March 2021 | X MOT Expired: 2 April 2021 |
|---|--|
| Tax status | Expired at 31 March 2021 |
| Days left | 1126 days too late |
| MOT expiry date | 2 April 2021 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 48 |
|---|------------|
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | |
| Date | OLE |
| Category | E.S. |
| Туре | |

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx | |
|---|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this AUDI had different number plates. | |
| Number of plates | 7 |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2007-04-27 |
| Last registration | 2020-04-03 |
| Complete history | See info |



| Registration #1 | 2007-04-27 | 17 mi |
|--|------------|--|
| Registration #2 | 2010-04-23 | 12.390 mi |
| Registration #3 | 2011-03-30 | 18.160 mi |
| Registration #4 | 2012-04-27 | 28.504 mi |
| Registration #5 | 2013-03-28 | 41.068 mi |
| Registration #6 | 2013-03-28 | 41.070 mi |
| Registration #7 | 2014-05-30 | 60.457 mi |
| Registration #8 | 2015-05-22 | 79.366 mi |
| | | |
| Registration #9 | | 11.777 mi |
| Registration #9 Registration #10 | | 00.000 est |
| - | | 01.000 est 01.000 est 01.000 est |
| Registration #10 | | 01.000 est 01.000 est 01.000 est 01.000 est |
| Registration #10 Registration #11 | | 01.000 440 01.000 440 01.000 440 01.000 440 01.000 440 |
| Registration #10 Registration #11 Registration #12 | | 00.000 460 0.000 460 00.000 460 00.000 460 00.000 460 00.000 460 |
| Registration #10 Registration #11 Registration #12 Registration #13 | | 00.000 460 0.000 460 0.000 460 0.000 460 0.000 460 0.000 460 0.000 460 |

More info >





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|---|--------------------------|
| Width | 1765 mm |
| Height | 1421 mm |
| Length | 4214 mm |
| Wheel base | 2578 mm |
| Max. allowed weight | 1880 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 55 I |
| | 55 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |

Engine number

BWA 065879