



Mercedes-Benz




report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	B-CLASS B160 SPORT
Colour	Black
Year of manufacture	2011
Top speed	104 mph
0 - 100 km/h	14.2 seconds
0 - 60 mph	14.2 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	70 kW / 95 HP / 95 BHP
Max. torque	140 Nm at 3.500 rpm
Engine capacity	1.498 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	45.6 mpg
Consumption combined	39.8 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 2


Date	2023-12-12
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-06-23
Pictures	24
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-21
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	24
Total items failed	0

MOT #11	2023-06-08 13:25
MOT test number	593978144253
Result	✓ Passed
Next expiry date	2024-06-21
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10	2022-06-22 09:02
MOT test number	806968867970
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing And low inner edge (5.2.3 (d) (ii))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Items removed from driver's view prior to test
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #9** 2022-06-15 09:59**MOT test number** 286969713511**Result** ✗ Failed**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Items removed from driver's view prior to test**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing And low inner edge (5.2.3 (d) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #8** 2021-06-16 13:36**MOT test number** 856768307509**Result** ✓ Passed**MOT #7** 2020-08-20 08:08**MOT test number** 513933678098**Result** ✓ Passed**MOT #6** 2019-08-13 08:24**MOT test number** 984318500510**Result** ✓ Passed

**MOT #5** 2018-08-28 14:26**MOT test number** 516760378351**Result** ✓ Passed**MOT #4** 2017-08-21 14:54**MOT test number** 159473618974**Result** ✓ Passed**MOT #3** 2016-08-17 09:31**MOT test number** 481158701366**Result** ✓ Passed**Advice** Rear Tyres perishing**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2015-09-08 09:32**MOT test number** 117746148940**Result** ✓ Passed**MOT #1** 2014-03-19 13:36**MOT test number** 145388174009**Result** ✓ Passed**Notice** Can't test rear seat belts child seat fitted**Notice** Both front brake disc starting to lip**Notice** Under-trays fitted obscuring some underside components



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
21 June 2024

Tax status	Valid until 1 July
Days left	64
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 YD11XLY
Plate since	2019-03-28
Current registration	 YD11XLY
Plate since	2019-03-28

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-03-23
Last registration	2023-06-08
Complete history	See info



Registration #1	2011-03-23	25 mi
Registration #2	2014-03-19	27.346 mi
Registration #3	2015-09-08	37.837 mi
Registration #4	2016-08-17	42.958 mi
Registration #5	2017-08-21	48.590 mi
Registration #6	2018-08-28	54.073 mi
Registration #7	2019-08-13	60.450 mi
Registration #8	2020-06-20	66.827 mi
Registration #9	2021-06-20	73.204 mi
Registration #10	2022-06-20	79.581 mi
Registration #11	2023-06-08	85.958 mi
Registration #12		
Registration #13		

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1350 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

26692030864943