



GU07NYG

report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA 16V SX
Colour	Beige
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-09-28
Pictures	10
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-07
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	21
Total items failed	27

MOT #20	2023-11-08 16:30
MOT test number	551748267087
Result	✓ Passed
Next expiry date	2024-11-07

MOT #19	2023-10-31 15:49
MOT test number	553430254340
Result	✗ Failed
Fail	Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill holed (7.1.1 (a) (i))
Fail	Horn not working (7.7 (a))
Fail	Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Nearside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))
Fail	Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

MOT #18	2022-10-05 14:39
MOT test number	836584489931
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17**

2022-09-27 10:54

MOT test number

865719677091

Result

✗ Failed

- Fail** Nearside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- Fail** Nearside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Headlamp aim not tested (4.1.2 (b))
- Advice** Centre exhaust box corroded
- Fail** Offside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))
- Fail** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))
- Fail** Nearside Headlamp aim too high (4.1.2 (a))
- Fail** Nearside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))

MOT #16

2021-10-01 09:24

MOT test number

694551546616

Result

✓ Passed

**MOT #15** 2021-09-29 15:35**MOT test number** 388723235498**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))**Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Side repeater not working (4.4.1 (a) (ii))**MOT #14** 2020-11-11 08:58**MOT test number** 749120411630**Result** ✓ Passed**MOT #13** 2019-05-20 14:39**MOT test number** 310650748703**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2018-05-18 11:44**MOT test number** 731632783617**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #11** 2017-04-05 13:10**MOT test number** 815330013897**Result** ✓ Passed

**MOT #10**

2017-04-05 09:37

MOT test number

161132099703

Result

✗ Failed

- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Rear Exhaust system not adequately supported (7.1.1)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Headlamp not working on dipped beam (1.7.5a)

MOT #9

2016-02-24 15:03

MOT test number

363275725789

Result

✓ Passed

- Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #8

2015-02-28 11:57

MOT test number

538449455025

Result

✓ Passed

MOT #7

2014-03-01 09:55

MOT test number

818560864024

Result

✓ Passed

- Notice** Offside front tyre worn on outer edge
- Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Notice** Rear tyres perished

**MOT #6** 2013-02-16 10:57**MOT test number** 876927343047**Result** ✓ Passed**MOT #5** 2013-02-16 10:57**MOT test number** 875017443018**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #4** 2012-02-22 12:17**MOT test number** 758563552000**Result** ✓ Passed**Notice** Rear tyres perished badly**MOT #3** 2012-02-22 09:13**MOT test number** 527853852089**Result** ✗ Failed**Notice** Rear tyres perished badly**Fail** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Horn not working (1.6.2a)**Fail** Offside Headlamp aim too low (1.8)**MOT #2** 2011-03-11 10:17**MOT test number** 786240771077**Result** ✓ Passed



MOT #1	2010-01-18 10:50
MOT test number	264898810080
Result	✓ Passed
Notice	Slight damage to n/s/r light lens
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
7 November 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	7 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-01
Last registration	2023-11-08
Complete history	See info



Registration #1	2007-03-01	27 mi
Registration #2	2010-01-18	15.497 mi
Registration #3	2011-03-11	24.181 mi
Registration #4	2012-02-22	30.314 mi
Registration #5	2012-02-22	30.314 mi
Registration #6	2013-02-16	33.911 mi
Registration #7	2014-03-01	38.720 mi
Registration #8	2015-02-28	41.986 mi
Registration #9	2016-02-24	45.196 mi
Registration #10	2017-04-05	49.732 mi
Registration #11	2017-04-05	49.732 mi
Registration #12	2018-04-05	53.977 mi
Registration #13	2019-04-05	58.222 mi
Registration #14	2020-04-05	62.467 mi
Registration #15	2021-04-05	66.712 mi
Registration #16	2022-04-05	70.957 mi
Registration #17	2023-04-05	75.202 mi
Registration #18	2023-11-08	79.447 mi
Registration #19	2023-11-08	79.447 mi
Registration #20	2023-11-08	79.447 mi
Registration #21	2023-11-08	79.447 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1667 mm
Height	1521 mm
Length	3850 mm
Wheel base	2460 mm
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6F3239543