



FL6IYEF

report date: 2024-03-28

General information

Make	NISSAN
Model	NAVARA DCI TEKNA 4X4 DCB
Colour	Grey
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	450 Nm at 2.000 rpm
Engine capacity	2.488 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.1 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-15
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-25
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	24
Total items failed	11

MOT #13	2023-09-26 13:39
MOT test number	805644993381
Result	✓ Passed
Next expiry date	2024-09-25
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12	2023-09-25 11:04
MOT test number	643735538886
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
Fail	Front Suspension arm ball joint excessively worn BOTH (5.3.4 (a) (i))
Fail	Front Position lamp not working both (4.2.1 (a) (ii))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #11	2022-07-29 11:59
MOT test number	659266781484
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

**MOT #10** 2022-07-28 13:10**MOT test number** 789180767247**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #9** 2021-01-13 15:46**MOT test number** 392750766580**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2021-01-12 11:39**MOT test number** 262641346756**Result** ✗ Failed**Fail** Front Emissions not tested Exhaust in to peaces (8.2.2.2 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Exhaust blow

**MOT #7** 2019-11-07 11:28**MOT test number** 895249524895**Result** ✓ Passed

- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2018-10-19 14:09**MOT test number** 292788985466**Result** ✓ Passed

- Minor** Central Front Windscreen damaged but not adversely affecting driver's view small stone chip (3.2 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Under body surface corrosion
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2017-10-10 16:19**MOT test number** 839536998792**Result** ✓ Passed**MOT #4** 2017-10-10 08:37**MOT test number** 753430838386**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)



MOT #3	2016-08-03 11:36
MOT test number	522209630470
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear Rear wheel bearing has slight play (2.6.2)
Advice	Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)
Advice	Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view door mirror (8.1.2a)
Advice	Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT #2	2015-07-16 17:30
MOT test number	458107795161
Result	✓ Passed

MOT #1	2014-09-15 14:41
MOT test number	219068654265
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 October 2024

✓  
**MOT**

**Expires:**  
25 September 2024

<b>Tax status</b>		Valid until 1 October
<b>Days left</b>		156
<b>MOT expiry date</b>		25 September 2024
<b>Full MOT history</b>		<a href="#">See MOT history</a>



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-30
Last registration	2023-09-26
Complete history	<a href="#">See info</a>



Registration #1	2011-09-30	24 mi
Registration #2	2014-09-15	31.730 mi
Registration #3	2015-07-16	36.087 mi
Registration #4	2016-08-03	58.048 mi
Registration #5	2017-10-10	80.938 mi
Registration #6	2017-10-10	80.938 mi
Registration #7	2018-10-19	95.622 mi
Registration #8	2019-11-07	109.224 mi
Registration #9	2020-05-20	121.277 mi
Registration #10	2020-05-20	121.277 mi
Registration #11	2020-05-20	121.277 mi
Registration #12	2020-05-20	121.277 mi
Registration #13	2020-05-20	121.277 mi
Registration #14	2020-05-20	121.277 mi
Registration #15	2020-05-20	121.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	10672B