





### General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	Grey
Year of manufacture	2012
Top speed	118 mph
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	194 BHP	0 < 101 A
Max. torque	436 Nm at 2.500 rpm	101 - 120 <sup>B</sup> <sub>C</sub>
Engine capacity	2.199 сс	121 - 140 E
Cylinders	4	141 - 165 F
Fuel type	Diesel	166 - 185
Consumption city	32.1 mpg	186 - 225
Consumption extra urban	45.6 mpg	225+
Consumption combined	39.2 mpg	
CO2 emission	197 g/km	
CO2 label	J	







# Internet history

E	nt	ry	1

Date Pictures 2021-09-15

47

Listing price

View report



source: cargurus.co.uk



### MOT history

MOT expiry date	2024-10-11
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	7
Total items failed	6

MOT #12	2023-10-12 13:07
MOT test number	306482581898
Result	✓ Passed
Next expiry date	2024-10-11

MOT #11	2022-10-05 10:19
MOT test number	676123562758
Result	🗸 Passed
Advice Nearside Front Play in steering rack inner joint(s)	

MOT #10	2021-10-09 14:07
MOT test number	675019008646
Result	✓ Passed

МОТ #9	2020-12-23 13:53
MOT test number	208298706482
Result	✓ Passed
Advice Nearside Play in steering rack inner joint(s)	
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely d	eteriorated (6.1.7 (g) (i))



<b>RO62XTA</b>
report date: 2024-03-28
2019-12-18 12:24

MOT test	number	387448391100
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Play in steering rack inner joint(s)	

# MOT #7

MOT #8

мот	test	number
-----	------	--------

MOT test number	327475033619
Result	🗙 Failed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Play in steering rack inner joint(s)	
<b>Fail</b> Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no lon ingress of dirt (6.1.7 (g) (ii))	ger prevents the
<b>Fail</b> Nearside Front Position lamp not working (4.2.1 (a) (ii))	

МОТ #6	2018-12-11 12:40
MOT test number	819358133445
Result	✓ Passed

MOT #5	2018-12-11 09:45
MOT test number	991839293760
Result	🗙 Failed
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	

MOT #4	2017-12-01 11:23
MOT test number	944018212760
Result	✓ Passed

2019-12-11 14:44





MOT #3		2016-10-13 10:10
MOT test number		454772106844
Result		✓ Passed
MOT #2		2015-10-07 14:38
MOT test number		875270725166
Result		✓ Passed
MOT #1		2015-10-07 14:38
MOT test number		342937933744
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too high (1.8)	
Pass with rectification	Offside Headlamp aim too low (1.8)	



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	MOT Expires: 11 October 2024
Tax status	Valid until 1 October
Days left	155
MOT expiry date	11 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date		
Category		Lamp
Туре		
Damage 2		ASMPL
Date		
Category	10000000	AMPL
Туре		

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
*******	
*********	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	8775-25-27
Current registration	
Plate since	







#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-09-26
Last registration	2023-10-12
Complete history	<u>See info</u>



Registration #1	2012-09-26	22 mi
Registration #2	2015-10-07	19.368 mi
Registration #3	2015-10-07	19.368 mi
Registration #4	2016-10-13	24.732 mi
Registration #5	2017-12-01	37.006 mi
Registration #6	2018-12-11	51.951 mi
Registration #7	2018-12-11	51.952 mi
Registration #8		11.777 esi
Registration #9		11.117 mi
Registration #10		10.207 est
Registration #10 Registration #11		11.517 es
-		01,000 est 01,000 est 01,000 est
Registration #11		0.000 es





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1890 mm
Height	1760 mm
Length	4685 mm
Wheel base	2700 mm
Kerb weight	1946 kg
Max. allowed weight	2570 kg
Additional information	
Fuel delivery	Direct Injection

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 12/12