



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I800 CRDI STYLE
Colour	Silver
Year of manufacture	2009
Top speed	112 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	392 Nm at 2.000 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	39.8 mpg
Consumption combined	33.2 mpg
CO2 emission	225 g/km
CO2 label	K





Internet history

Entry 2

Date	2023-10-04
Pictures	36
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-12-14
Pictures	3
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-03-30
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	46
Total items failed	9

MOT #172023-03-08 15:32

MOT test number450818865524

Result✓ Passed

Next expiry date2024-03-30

- Advice

Central Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice

Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Central Front Fluid leak, but not excessive steering rack (8.4.1 (a) (i))
- Advice

Offside Front Service brake binding but not excessively (1.2.1 (f))
- Advice

Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16**

2023-03-06 16:28

MOT test number

807379417420

Result**✗ Failed****Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Central Front Fluid leak, but not excessive steering rack (8.4.1 (a) (i))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**MOT #15**

2022-03-31 11:42

MOT test number

268465725733

Result**✓ Passed****Advice** Vehicle in need of a full brake service.**MOT #14**

2022-01-05 16:36

MOT test number

772321829571

Result**✓ Passed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

**MOT #13**

2022-01-04 15:33

MOT test number

757204122888

Result

✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #12**

2021-02-25 16:49

MOT test number

531181592209

Result

✓ Passed

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11**

2021-02-24 14:07

MOT test number

973848553958

Result

✗ Failed

Fail Brake performance not tested (1.2.1 (g))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**MOT #10**

2020-02-29 10:10

MOT test number

652579782281

Result

✓ Passed

**MOT #9** 2018-09-24 09:11**MOT test number** 597482643499**Result** ✓ Passed

- Advice** Offside Play in steering rack inner joint(s)
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge Also perished (5.2.3 (e))
- Advice** Nearside Front Tyre perished but not yet down to cords
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8 2017-09-29 09:32**MOT test number** 950696289402**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2017-09-25 14:05**MOT test number** 952472837625**Result** ✗ Failed

- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Advice** Play in steering rack inner joint(s)
- Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)
- Advice** Nearside Front Tyre worn close to the legal limit and o/s/f inner edge (4.1.E.1)



MOT #6	2016-12-16 12:29
MOT test number	207958518418
Result	✓ Passed

MOT #5	2015-12-10 12:37
MOT test number	224540163281
Result	✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Slight play in both inner tie rods
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4	2015-12-10 10:53
MOT test number	159011918113
Result	✗ Failed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Slight play in both inner tie rods
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)



MOT #3	2015-04-21 11:51
MOT test number	898131615147
Result	✓ Passed

MOT #2	2013-11-29 09:35
MOT test number	448593533453
Result	✓ Passed
<div><div>Advice</div> Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)</div> <div><div>Advice</div> Front Brake pad(s) wearing thin (3.5.1g)</div>	

MOT #1	2012-12-07 14:24
MOT test number	406112542432
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
9 August 2023

X

MOT

Expired:
30 March 2024

Tax status	Expired at 9 August 2023
Days left	263 days too late
MOT expiry date	30 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EA59OHU
Plate since	2019-09-29
Current registration	EA59OHU
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-12-10
Last registration	2023-03-08
Complete history	See info



Registration #1	2009-12-10	20 mi
Registration #2	2012-12-07	25.294 mi
Registration #3	2013-11-29	32.630 mi
Registration #4	2015-04-21	43.727 mi
Registration #5	2015-12-10	51.264 mi
Registration #6	2015-12-10	51.264 mi
Registration #7	2016-12-16	62.640 mi
Registration #8	2017-09-25	69.502 mi
Registration #9	2017-09-29	69.503 mi
Registration #10	2018-09-24	75.702 mi
Registration #11	2019-05-29	81.377 mi
Registration #12	2019-05-29	81.377 mi
Registration #13	2019-05-29	81.377 mi
Registration #14	2019-05-29	81.377 mi
Registration #15	2019-05-29	81.377 mi
Registration #16	2019-05-29	81.377 mi
Registration #17	2019-05-29	81.377 mi
Registration #18	2019-05-29	81.377 mi
Registration #19	2019-05-29	81.377 mi
Registration #20	2019-05-29	81.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1920 mm
Height	1925 mm
Length	5125 mm
Wheel base	3200 mm
Kerb weight	2270 kg
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

Number of axles	2
Engine number	D4CB8394448