





report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO L2H1 2900 SPORTIVE CDTI BITURBO S/S
Colour	Black
Year of manufacture	2017
Top speed	100 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	46.3 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-10-11

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-03
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	3

MOT #5		2023-10-17 08:10
MOT test	number	663374698699
Result		✓ Passed
Next expi	ry date	2024-11-03
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Central Child Seat fitted not allowing full inspection of adult belt	

MOT #4	2022-11-04 12:09
MOT test number	483140034742
Result	✓ Passed
MOT #3	2021-11-02 15:34
MOT test number	654458047063
Result	√ Passed

MOT #2	2020	-12-23 15:36
MOT test	t number 88	2144548842
Result		✓ Passed
Minor	Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Minor	Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2020-12-23 12:11

MOT test number 920637554021

Result X Failed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check





Tax status	Valid until 1 February
Days left	279
MOT expiry date	3 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28


Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra VAUXHALL salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history

e mier metery	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlondere.	

Plate changes	More info >
See in this check if this VAUXHALL had different number plates.	
Number of plates	
Current registration	NK NY
Plate since	
Current registration	NK NK
Plate since	110-0-0

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-12-19
Last registration	2023-10-17
Complete history	See info



Registration #1	2017-12-19	22 mi
Registration #2	2020-12-23	43.359 mi
Registration #3	2020-12-23	43.360 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5398 mm
Wheel base	3498 mm
Kerb weight	1760 kg
Max. allowed weight	3040 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	R9M D4 - C281414LQI

CarCheck.co.uk page 11/11