





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE GTI
Colour	Silver
Year of manufacture	2000
Top speed	121 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
	113 5
Max. torque	170 Nm at 3.200 rpm
Engine capacity	2.000 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg



CarCheck.co.uk page 1/10



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-31

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

MOT history

MOT expiry date	2024-08-23
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	8
Total items failed	0

MOT #5		2023-08-23 15:50
MOT test	number	688107181897
Result		✓ Passed
Next expi	ry date	2024-08-23
Advice old (5.2.3	Offside Front Tyre worn close to legal limit/worn on edge Bald on oute	r edge, tyre is also 19 years
Advice	Nearside Play in steering rack inner joint(s)	
Advice	Vehicles internal headlight adjuster altered to recheck lights	
Advice	Nearside Rear Tyre is 12 years old	

MOT #4		2022-08-08 10:49
MOT test	number	236267317663
Result		✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #3	2021-08-24 14:10
MOT test number	509453495651
Result	✓ Passed

CarCheck.co.uk page 3/10



(i))

L800BUG

report date: 2024-03-28

MOT #2 2020-01-18 09:13 MOT test number 775621373045

Result ✓ Passed

MOT #1 2019-01-07 13:39

MOT test number 578835096690

Result
✓ Passed

Advice Nearside Front Upper Suspension component pin or bush slightly worn top mount bush (5.3.4 (a)

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/10



report date: 2024-03-28

Tax & MOT check



Days left 34

MOT expiry date 23 August 2024

Full MOT history See MOT history

CarCheck.co.uk page 5/10



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

Owner history

e when moterly	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

2000000	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NIC NIC
Plate since	
	More info

CarCheck.co.uk page 7/10



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2000-08-01
Last registration	2023-08-23
Complete history	See info



Registration #1	2000-08-01	17 mi
Registration #2	2019-01-07	44.448 mi
Registration #3	2020-01-18	47.818 mi
Registration #4	2021-08-24	48.679 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		D.777 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1735 mm
Height	1439 mm
Length	4149 mm
Wheel base	2511 mm
Max. allowed weight	1505 kg

Additional information

-	
Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2

CarCheck.co.uk page 10/10

Engine number

APK704916