





report date: 2024-03-29

## General information

Make	JAGUAR
Model	XF D LUXURY SPORTBRAKE
Colour	Black
Year of manufacture	2014
Top speed	130 mph
0 - 60 mph	10.0 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	163 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/10



MOT history

MOT expiry date	2024-09-17
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	4
Total items failed	5

MOT #8	2023-09-18 12:51
MOT test number	937929050475
Result	<b>✓</b> Passed
Next expiry date	2024-09-17
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2022-09-05 12:32
MOT test	number 763422218393
Result	✓ Passed
Advice	Tyre worn close to legal limit/worn on edge Both rears wearing around inner shoulders (5.2.3 (e))
Advice	Tyre worn close to legal limit/worn on edge Both rears wearing around inner shoulders (5.2.3 (e))

MOT #6	2021-09-11 10:56
MOT test number	635914165770
Result	✓ Passed
Advice Front Tyre worn close to legal limit/worn on edge o/s & n/s o perished on the side walls and very worn on the edges and the cords will be showing soon (5.2.3 (e))	

MOT #5	2020-09-11 13:37
MOT test number	692627264417
Result	✓ Passed

CarCheck.co.uk page 2/10



Fail

RV64RYY report date: 2024-03-29

MOT #	÷ <b>4</b>	2019-09-12 14:17
MOT te	est number	574485709397
Result		✓ Passed
MOT #	3	2019-09-12 11:03
MOT te	est number	386976650280
Result		× Failed
Fail	Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Offside Front Tyre has a lump, caused by separation or partial failure of its struc	ture (5.2.3 (d) (ii))

MOT #2		2018-03-15 13:32
MOT test number		828145850041
Result		✓ Passed
MOT #1		2018-03-15 13:32
MOT test number		962495266733
Result		<b>X</b> Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)	

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 3/10



## Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	17 September 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 4/10



**RV64RYY** 

report date: 2024-03-29

#### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



#### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

e when miscory		
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		₹
THE PARTY OF THE P		
***************************************		
	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	OK SIE	
Plate since		
Current registration	OK ONE	
Plate since		
	More info	>

CarCheck.co.uk page 7/10



#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-09-26
Last registration	2023-09-18
Complete history	See info



Registration #1	2014-09-26	8 mi
Registration #2	2018-03-15	29.321 mi
Registration #3	2018-03-15	29.321 mi
Registration #4	2019-09-12	39.565 mi
Registration #5	2019-09-12	39.569 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 9/10



# Safety ratings

NCAP rating	***
Adult	79%
Children	73%
Pedestrian	62%
Safety systems	71%
Overall rating	74%
Video	see crash video



# Dimensions & weight

Width	1920 mm
Height	1480 mm
Length	4966 mm
Wheel base	2909 mm
Kerb weight	1824 kg
Max. allowed weight	2320 kg

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	4003538224DT

CarCheck.co.uk page 10/10