



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TIGUAN SE NAV TDI BMT
Colour	Grey
Year of manufacture	2018
Top speed	127 mph
0 - 100 km/h	9.3 seconds
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 kW / 150 HP / 148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	125 g/km
CO2 label	D





Internet history

Entry 2



Date	2021-07-10
Pictures	35
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-09
Pictures	35
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-01
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	16
Total items failed	2

MOT #6	2023-06-30 14:47
MOT test number	918085195349
Result	✓ Passed
Next expiry date	2024-07-01
Advice	Front Shock absorbers has light misting of oil both (5.3.2 (b))
Advice	Rear Inner Brake pad(s) wearing thin inner pads appear low (1.1.13 (a) (ii))

MOT #5	2023-06-29 11:24
MOT test number	704476450322
Result	✗ Failed
Advice	Rear Inner Brake pad(s) wearing thin inner pads appear low (1.1.13 (a) (ii))
Fail	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Front Shock absorbers has light misting of oil both (5.3.2 (b))

MOT #4	2022-06-30 09:42
MOT test number	954868542609
Result	✓ Passed

MOT #3	2021-07-02 13:53
MOT test number	576761496348
Result	✓ Passed

**MOT #2**

2021-06-01 13:53

MOT test number

801327197776

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1

2021-06-01 09:03

MOT test number

379507434082

Result

✗ Failed

- Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
1 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	1 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YF18ZTL
Plate since	2019-03-29
Current registration	 YF18ZTL
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-05-23
Last registration	2023-06-30
Complete history	See info



Registration #1	2018-05-23	7 mi
Registration #2	2021-06-01	39.648 mi
Registration #3	2021-06-01	39.648 mi
Registration #4	2021-07-02	39.663 mi
Registration #5	2023-06-30	39.663 mi
Registration #6	2023-06-30	39.663 mi
Registration #7	2023-06-30	39.663 mi
Registration #8	2023-06-30	39.663 mi
Registration #9	2023-06-30	39.663 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	84%
Pedestrian	72%
Safety systems	68%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2099 mm
Height	1632 mm
Length	4486 mm
Wheel base	2681 mm
Kerb weight	1568 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	DFGA845412