




report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO BLUEHDI FEEL ETG6
Colour	Grey
Year of manufacture	2018
Top speed	106 mph
0 - 60 mph	14.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	68.9 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B







Internet history

Entry 2

Date	2021-10-12
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-10-11
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)





MOT history

MOT expiry date	2024-11-28
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	19
Total items failed	9

MOT #7	2023-11-29 12:41
MOT test number	821132554009
Result	✓ Passed
Next expiry date	2024-11-28
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



**MOT #6**

2023-11-28 13:18

**MOT test number**

114001415351

**Result****✗ Failed**

- Minor** Nearside Rear Tyre obviously under inflated (5.2.3 (l))
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Brake pedal anti-slip provision missing (1.1.2 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))
- Fail** Windscreen washer not working (3.5 (a))

**MOT #5**

2022-10-26 14:00

**MOT test number**

494255433832

**Result****✓ Passed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



**MOT #4** 2022-10-26 09:09**MOT test number** 182769765186**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2021-11-19 16:51**MOT test number** 743303882169**Result** ✓ Passed**MOT #2** 2021-05-10 12:26**MOT test number** 704722941563**Result** ✓ Passed**MOT #1** 2021-05-10 10:44**MOT test number** 100447774219**Result** ✗ Failed**Fail** Windscreen washer not working (3.5 (a))





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
28 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	28 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>First licence fee (12 months)</b>	£ 185,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 210,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX


More info >





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-06-15
Last registration	2023-11-29
Complete history	<a href="#">See info</a>



Registration #1	2018-06-15	12 mi
Registration #2	2021-05-10	12.617 mi
Registration #3	2021-05-10	12.617 mi
Registration #4	2023-05-29	12.617 mi
Registration #5	2023-05-29	12.617 mi
Registration #6	2023-05-29	12.617 mi
Registration #7	2023-05-29	12.617 mi
Registration #8	2023-05-29	12.617 mi
Registration #9	2023-05-29	12.617 mi
Registration #10	2023-05-29	12.617 mi

More info >





Safety ratings

NCAP rating	★★★★☆	▢
Adult	56%	
Children	74%	
Pedestrian	63%	
Safety systems	48%	
Overall rating	59%	
Video	<a href="#">see crash video</a>	

Dimensions & weight

Width	1810 mm
Height	1852 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1399 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	JBHW3030220