





report date: 2024-03-29

General information

| Make | AUDI |
|---------------------|------------------------|
| Model | TT TFSI |
| Colour | White |
| Year of manufacture | 2008 |
| Top speed | 147 mph |
| 0 - 60 mph | 6.5 seconds |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| Power | 197 BHP |
|-------------------------|---------------------|
| Max. torque | 280 Nm at 1.800 rpm |
| Engine capacity | 1.984 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 26.2 mpg |
| Consumption extra urban | 46.3 mpg |
| Consumption combined | 36.2 mpg |
| CO2 emission | 186 g/km |
| CO2 label | J |



CarCheck.co.uk page 1/13



LR58UTX report date: 2024-03-29

Internet history

Entry 1

Date 2021-06-05

Pictures 33

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



LR58UTX
report date: 2024-03-29

MOT history

| MOT expiry date | 2024-05-13 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 12 |
| Failed MOT tests | 3 |
| Total advice items | 19 |
| Total items failed | 4 |

| MOT #15 | 2023-05-03 11:46 |
|---|------------------|
| MOT test number | 509500143995 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-13 |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #14 | | 2022-05-14 09:05 |
|----------|---|------------------|
| MOT test | number | 408522640625 |
| Result | | ✓ Passed |
| Advice | Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13 2021-02-17 14:40 **MOT** test number 673853659534 ✓ Passed Result **Advice** Rear Coil spring corroded (5.3.1 (b) (i)) **Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Small chips in windscreen Advice Nearside Rear tyre cracking inside tread and outer sidewall damaged Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Oil leak on engine, looks like from oil filter

MOT #12 2020-02-21 14:33 **MOT** test number 576560580082 Result ✓ Passed **MOT #11** 2019-04-26 15:04 **MOT** test number 366490974060 Result ✓ Passed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number
627398962590

Result

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Position lamp not working (4.2.1 (a))

CarCheck.co.uk page 4/13



report date: 2024-03-29

✓ Passed

MOT #9 2018-06-29 08:31

MOT test number 121023053335

Result
✓ Passed

MOT #8 2018-06-27 09:29

MOT test number 749498687819

Result X Failed

Fail Nearside Front Anti-roll bar linkage ball joint dust cover missing (5.3.4 (b) (ii))

MOT #7 2017-06-29 14:36

MOT test number 152027575196

Result ✓ Passed

MOT #6 2016-06-09 14:41

MOT test number 422081691843

Result ✓ Passed

MOT #5 2016-06-09 13:48

MOT test number 571104196112

Result X Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #4 2015-06-15 10:18

MOT test number 318496865167

310 130003107

Notice Under-trays fitted obscuring some underside components

Result

CarCheck.co.uk page 5/13



report date: 2024-03-29

| MOT #3 | 2014-03-03 12:39 |
|---|------------------|
| MOT test number | 358202264051 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin (3.5.1g) | |
| Advice Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Front Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #2 | | 2012-09-12 14:26 |
|----------|--|------------------|
| MOT test | number | 179896352279 |
| Result | | ✓ Passed |
| Notice | Engine covers fitted obscuring some components in the engine bay | |
| Notice | Under-trays fitted obscuring some underside components | |

| MOT #1 | 2011-09-30 17:57 |
|-----------------|------------------|
| MOT test number | 689573771212 |
| Result | ✓ Passed |

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 June |
|------------------|--------------------|
| Days left | 32 |
| MOT expiry date | 13 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



LR58UTX
report date: 2024-03-29

Owner history

| Owner history | |
|--|-------------|
| For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report | |
| ************************************** | |
| *************************************** | |
| THE STREET STREET | |
| *************************************** | |
| | |
| ************* | |
| | More info > |
| Plate changes | |
| See in this check if this AUDI had different number plates. | |
| Number of plates | , |
| Current registration | UK NEE |
| Plate since | |
| Current registration | NE NE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2008-09-30 |
| Last registration | 2023-05-03 |
| Complete history | See info |



| Registration #1 | 2008-09-30 | 6 mi |
|------------------|------------|-----------|
| Registration #2 | 2011-09-30 | 19.963 mi |
| Registration #3 | 2012-09-12 | 28.272 mi |
| Registration #4 | 2014-03-03 | 40.933 mi |
| Registration #5 | 2015-06-15 | 46.052 mi |
| Registration #6 | 2016-06-09 | 49.485 mi |
| Registration #7 | 2016-06-09 | 49.485 mi |
| Registration #8 | 2017-06-29 | 58.377 mi |
| Registration #9 | 2018-06-27 | 68.374 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | D.777-ec |
| | | |
| Registration #16 | | 11.777 46 |

More info >

CarCheck.co.uk page 12/13



LR58UTX
report date: 2024-03-29

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1842 mm |
|---------------------|---------|
| Height | 1358 mm |
| Length | 4178 mm |
| Wheel base | 2468 mm |
| Kerb weight | 1315 kg |
| Max. allowed weight | 1635 kg |

Additional information

| Fuel tank capacity | 55 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 2 |
| Number of seats CarCheck.co.uk | 2 page 13, |