



report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	Black
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-12
Pictures	18
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-26
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	31
Total items failed	16

MOT #19	2024-02-19 13:40
MOT test number	641715409760
Result	✓ Passed
Next expiry date	2025-02-26
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #18	2024-02-19 10:38
MOT test number	611079272528
Result	✗ Failed
Fail	Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Fail	Front Windscreen washer not working (3.5 (a))
Minor	Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17**

2023-02-18 11:55

**MOT test number**

392784075573

**Result**

✓ Passed

- Advice** Offside Front Valve stem slightly damaged (5.2.3 (j))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases weld on back box (6.1.2 (a))
- Advice** Offside Rear Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))

**MOT #16**

2022-02-16 12:50

**MOT test number**

102709349867

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2022-02-15 12:12

**MOT test number**

706639591332

**Result**

✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Inner Steering linkage ball joint has excessive play tie rod (2.1.3 (b) (i))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #14**

2021-02-27 11:52

**MOT test number**

934661230729

**Result**

✓ Passed

**MOT #13**

2020-02-28 10:42

**MOT test number**

177075141267

**Result**

✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12**

2020-02-26 15:50

**MOT test number**

863739252326

**Result**

✗ Failed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #11**

2019-03-28 12:30

**MOT test number**

521236692611

**Result**

✓ Passed

**MOT #10** 2018-02-28 15:28**MOT test number** 922929809150**Result** ✓ Passed**Advice** Rear axle starting rust**Advice** Rear Shock absorber has a slightly worn bush (2.7.4)**MOT #9** 2017-03-03 17:25**MOT test number** 212611475964**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases flexy pipe (7.1.2)**MOT #8** 2017-03-03 12:02**MOT test number** 107761101994**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Exhaust has a minor leak of exhaust gases flexy pipe (7.1.2)**Fail** Offside rear brake recording little or no effort (3.7.B.5a)**Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)**Fail** Offside Rear Braking system leaking wheel cylinder (3.6.A.1)**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure 175/65/14 (4.1.D.1b)**MOT #7** 2016-03-10 15:12**MOT test number** 969122829699**Result** ✓ Passed

**MOT #6** 2016-03-09 14:40**MOT test number** 975185902619**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside Rear rear brake recording little or no effort hand brake (3.7.B.5a)**MOT #5** 2015-02-06 09:55**MOT test number** 377387435003**Result** ✓ Passed**MOT #4** 2014-01-23 10:36**MOT test number** 378413024033**Result** ✓ Passed**Notice** Back box is peeling**MOT #3** 2013-01-24 16:12**MOT test number** 167724323467**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-01-24 12:13**MOT test number** 125684723420**Result** ✗ Failed**Fail** Offside Front Windscreen wiper blade insecure (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Rear registration plate deteriorated (6.3.1d)



MOT #1	2012-01-27 10:07
MOT test number	609307722048
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
26 February 2025

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	26 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-01-31
Last registration	2024-02-19
Complete history	<a href="#">See info</a>



Registration #1	2009-01-31	16 mi
Registration #2	2012-01-27	26.439 mi
Registration #3	2013-01-24	28.850 mi
Registration #4	2013-01-24	28.850 mi
Registration #5	2014-01-23	34.199 mi
Registration #6	2015-02-06	37.413 mi
Registration #7	2016-03-09	44.758 mi
Registration #8	2016-03-10	44.778 mi
Registration #9	2017-03-03	52.305 mi
Registration #10	2017-03-03	52.305 mi
Registration #11	2018-02-28	57.513 mi
Registration #12	2019-03-03	62.721 mi
Registration #13	2020-03-03	67.929 mi
Registration #14	2021-03-03	73.137 mi
Registration #15	2022-03-03	78.345 mi
Registration #16	2023-03-03	83.553 mi
Registration #17	2024-02-19	88.761 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	5187434