




report date: 2024-03-28

General information

Make	VAUXHALL
Model	GRANDLAND ELITE NAV S/S
Colour	Black
Year of manufacture	2018
Top speed	117 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption


Power	130 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	57.6 mpg
Consumption combined	54.3 mpg
CO2 emission	124 g/km
CO2 label	D



Internet history

Entry 4



Date	2021-07-25
Pictures	10
Listing price	View report



source: [yesauto.com](#)

Entry 3

Date	2021-06-29
Pictures	50
Listing price	View report



source: [heyicar.co.uk](#)

Entry 2

Date	2021-06-29
Pictures	58
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-15
------	------------

Pictures

0

Listing price

[View report](#)

source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-29
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	15
Total items failed	0

MOT #4	2024-04-12 15:58
MOT test number	939256152282
Result	✓ Passed
Next expiry date	2025-04-29
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3	2023-04-05 09:48
MOT test number	956433478131
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #2 2022-04-01 10:37

MOT test number 292732800294

Result ✓ Passed

Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #1 2021-04-22 10:47

MOT test number 529772332121

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2024

✓
MOT

Expires:
29 April 2025

Tax status Valid until 1 August

Days left 94

MOT expiry date 29 April 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates 1

Current registration  **XXXXXXXXXX**

Plate since 2019-09-29

Current registration  **XXXXXXXXXX**

Plate since 2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-04-30
Last registration	2024-04-12
Complete history	See info



Registration #1	2018-04-30	29 mi
Registration #2	2021-04-22	16.720 mi
Registration #3	2019-05-01	16.720 mi
Registration #4	2019-05-01	16.720 mi
Registration #5	2019-05-01	16.720 mi
Registration #6	2019-05-01	16.720 mi
Registration #7	2019-05-01	16.720 mi
Registration #8	2019-05-01	16.720 mi
Registration #9	2019-05-01	16.720 mi

[More info >](#)



Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	87%
Pedestrian	63%
Safety systems	60%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1856 mm
Height	1630 mm
Length	4477 mm
Wheel base	2675 mm
Kerb weight	1350 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	10XTA10908686 LES