




report date: 2024-03-28

General information

Make	FORD
Model	S-MAX EDGE TDCI
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.3 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	189 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-08-13
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-25
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	61
Total items failed	5

MOT #15	2024-01-26 09:54
MOT test number	228456312544
Result	✓ Passed
Next expiry date	2025-01-25
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #14**

2024-01-26 08:40

MOT test number

979558928277

Result**✗ Failed**

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Front Service brake imbalanced across an axle (1.2.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))

MOT #13

2022-11-30 09:07

MOT test number

576118391977

Result**✓ Passed**

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension component pin or bush slightly worn training arm (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension component pin or bush slightly worn training arm (5.3.4 (a) (i))

**MOT #12**

2022-02-22 09:11

MOT test number

570620860484

Result

✓ Passed

- Advice** Nearside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i))
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Suspension component pin or bush slightly worn trailing arm (5.3.4 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11

2021-02-09 15:41

MOT test number

559116090718

Result

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Devoid of tread on extreme edges. Tyre size - 225 50 ZR17 98Y extra load. (5.2.3 (e))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush slightly separating. (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect Limited damping effect. (5.3.2 (b))
- Advice** Rear Inner Brake pad(s) wearing thin Pads appear worn but view is restricted with wheels on. (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Devoid of tread on extreme edges. (5.2.3 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush slightly separating. (5.3.4 (a) (i))
- Advice** Nearside Front Service brake binding but not excessively Causing a reading of 40% maximum brake imbalance. (1.2.1 (f))

**MOT #10**

2021-02-09 08:19

MOT test number

385837754525

Result**✗ Failed**

Advice Rear Inner Brake pad(s) wearing thin Pads appear worn but view is restricted with wheels on.
(1.1.13 (a) (ii))

Advice Nearside Front Service brake binding but not excessively Causing a reading of 40% maximum
brake imbalance. (1.2.1 (f))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Devoid of tread on extreme edges.
(5.2.3 (e))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect Limited damping
effect. (5.3.2 (b))

Fail Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing
arm bush slightly separating. (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Devoid of tread on extreme edges. Tyre
size - 225 50 ZR17 98Y extra load. (5.2.3 (e))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt
(5.3.4 (b) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing
arm bush slightly separating. (5.3.4 (a) (i))

MOT #9

2020-01-31 10:43

MOT test number

151314159679

Result**✓ Passed**

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #8

2019-01-25 15:13

MOT test number

282691030252

Result**✓ Passed**

Advice

Nearside Front Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**MOT #7** 2018-01-26 10:22**MOT test number** 327255073514**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 2mm 225/50-17 (4.1.E.1)**MOT #6** 2017-01-27 13:08**MOT test number** 202786611128**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit 225/50/r17/98y/xl@2mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #5** 2016-01-29 15:25**MOT test number** 408815090629**Result** ✓ Passed**Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-01-29 10:07**MOT test number** 250125607628**Result** ✗ Failed**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Rear Inner Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #3** 2015-01-30 12:58**MOT test number** 709040235037**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components

MOT #2 2014-01-29 10:39**MOT test number** 269369524033**Result** ✓ Passed**MOT #1** 2013-02-22 08:43**MOT test number** 707013553063**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
31 December 2023

✓

MOT

Expires:
25 January 2025

Tax status	Expired at 31 December 2023
Days left	120 days too late
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-02-22
Last registration	2024-01-26
Complete history	See info



Registration #1	2010-02-22	13 mi
Registration #2	2013-02-22	30.467 mi
Registration #3	2014-01-29	38.411 mi
Registration #4	2015-01-30	47.356 mi
Registration #5	2016-01-29	55.128 mi
Registration #6	2016-01-29	55.128 mi
Registration #7	2017-01-27	63.749 mi
Registration #8	2018-01-26	71.759 mi
Registration #9	2019-01-25	82.106 mi
Registration #10	2020-01-25	91.277 mi
Registration #11	2021-01-25	100.448 mi
Registration #12	2022-01-25	109.619 mi
Registration #13	2023-01-25	118.790 mi
Registration #14	2024-01-26	127.961 mi
Registration #15	2024-01-26	127.961 mi
Registration #16	2024-01-26	127.961 mi
Registration #17	2024-01-26	127.961 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Max. allowed weight	2505 kg

Additional information

Number of seats	7
Number of axles	2
Engine number	9E15196