





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SE TSI
Colour	White
Year of manufacture	2015
Top speed	114 mph
0 - 100 km/h	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	66 kW / 90 HP / 89 BHP
Max. torque	160 Nm at 1.400 rpm
Engine capacity	1.197 сс
Cylinders	4
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	107 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-10-15

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-19
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	17
Total items failed	0

MOT #7		2023-11-08 14:18
MOT test	number	432230189161
Result		✓ Passed
Next exp	iry date	2024-11-19
Minor	Nearside Front Outer Anti-roll bar linkage ball joint dust cover severely de	teriorated (5.3.4 (b) (i))
Advice Brake pipe corroded, covered in grease or other material nearside and offside front to rear (1.1.11 (c))		
Advice	Offside Rear Nail in tyre	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1	.1.11 (c))

MOT #6		2023-11-08 12:56
MOT test	number	440993171006
Result		X Failed
Advice	Offside Rear Nail in tyre	
Advice (c))	Brake pipe corroded, covered in grease or other material nearside and off	fside front to rear (1.1.11
Minor	Nearside Front Outer Anti-roll bar linkage ball joint dust cover severely det	eriorated (5.3.4 (b) (i))
MAJOR	Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4	l (a) (i))
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.3	1.11 (c))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5 2022-11-14 09:33

MOT test number 972161849812

Result ✓ Passed

Advice Brake pipe corroded, covered in grease or other material nearside ands offside front to rear rear section (1.1.11 (c))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #4 2021-11-04 08:51

MOT test number 364982275132

MOT #3 2020-11-19 09:41

MOT test number 735898754459

Result

Passed

MOT #2 2019-10-25 09:36

MOT test number 282587339960

Result \(\sqrt{Passed} \)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2018-10-26 13:14

MOT test number 635612375949

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 19 November 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	19 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-11-20
Last registration	2023-11-08
Complete history	See info



Registration #1	2015-11-20	9 mi
Registration #2	2018-10-26	31.367 mi
Registration #3	2019-10-25	39.925 mi
Registration #4	2020-11-19	47.378 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



VN65OKM report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1453 mm
Length	3972 mm
Wheel base	2470 mm
Kerb weight	1107 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	5
Number of axles	2
Engine number	CJZC730965