





report date: 2024-03-29

General information

Make	MERCEDES
Model	VITO 111 CDI LONG P/V
Colour	White
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	116 BHP
Engine capacity	2.148 сс
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/11




Internet history

Entry 1

Date 2021-11-24

Pictures 32

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-10-18
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	3
Total items failed	9

MOT #6	2023-10-13 13:58
MOT test number	474119720988
Result	✓ Passed
Next expiry date	2024-10-18
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #5	2023-10-13 10:57
MOT test number	805022066528
Result	X Failed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	

MOT #4	2022-10-19 14:37
MOT test number	573195263515
Result	√ Passed

CarCheck.co.uk page 3/11



GN10FYY

report date: 2024-03-29

MOT #3	2022-09-29 08:40
MOT test number	775063579555
Result	X Failed
Fail Offside Rear fog lamp not working (4.5.1 (a) (ii))	
Fail Offside Headlamp not working on main beam (4.1.1 (a) (ii))	
Fail Nearside Headlamp not working on main beam (4.1.1 (a) (ii))	

MOT #2	2021-10-13 11:41
MOT test number	396047998432
Result	✓ Passed

MOT #		2021-10-11 15:30
MOT te	st number	529162955237
Result		× Failed
Fail	Offside Front Anti-roll bar ball joint dust cover missing (5.3.4 (b) (ii))	
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Fail	Central Stop lamp(s) not working (4.3.1 (a) (ii))	
Advid	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail	Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of	of dirt (5.3.4 (b) (ii))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

CarCheck.co.uk page 4/11



Tax & MOT check



MOT expiry date 18 October 2024

Full MOT history See MOT history

CarCheck.co.uk page 5/11



GN10FY

report date: 2024-03-29


Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra MERCEDES salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NIE NIE
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2010-07-09
Last registration	2023-10-13
Complete history	See info



Registration #1	2010-07-09	20 mi
Registration #2	2021-10-11	113.766 mi
Registration #3	2021-10-13	113.766 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71,777 es

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	***
Video	see crash video



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Engine number	64698051841693

CarCheck.co.uk page 11/11