





report date: 2024-03-29

#### General information

Make	JAGUAR
Model	X-TYPE SOVEREIGN
Colour	Grey
Year of manufacture	-
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	129 BHP
Max. torque	331 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg



CarCheck.co.uk page 1/14



# Internet history


#### Entry 1

Date 2021-06-25

Pictures 29

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



**MOT** history

**MOT #17** 2021-06-23 09:53

**MOT test number** 698632799708

**Result** ✓ Passed

Next expiry date 2022-06-22

**MOT #16** 2021-06-17 15:48

**MOT test number** 782929573048

**Result** X Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))

**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

**MOT #15** 2020-09-03 15:05

**MOT test number** 348816615152

Result J Passed

Advice Front brake discs corroded /worn

**MOT #14** 2020-09-01 15:41

MOT test number 261922490362

**Result** ★ Failed

**Advice** Front brake discs corroded /worn

Fail Nearside Rear Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))

MOT #13 2019-08-23 08:23

MOT test number 384106429038

CarCheck.co.uk page 3/14



2018-08-31 11:15

MOT test number 278963121539

**Result** ✓ Passed

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Minor Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4

(b))

(b))

**MOT #12** 

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4

Minor Offside Front Brake hose slightly chafed (1.1.12 (b) (i))

**MOT #11** 2018-08-20 14:01

MOT test number 970072273724

**Result** X Failed

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail Nearside Front Headlamp light source and lamp not compatible hid conversion (4.1.4 (c))

Minor Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Nearside Rear Brake pipe excessively corroded flexi pipe (1.1.11 (c))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Offside Front Headlamp light source and lamp not compatible hid conversion (4.1.4 (c))

Minor Offside Front Brake hose slightly chafed (1.1.12 (b) (i))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Fail** Offside Rear Brake pipe excessively corroded flexi pipe (1.1.11 (c))

CarCheck.co.uk page 4/14



FY57DYA

report date: 2024-03-29

**MOT #10** 2017-08-30 14:34

**MOT test number** 548413183939

Result ✓ Passed Advice Body has slight corrosion (6.1.B.2) Offside Front Brake hose slightly deteriorated (3.6.B.4d) Advice Advice Offside Rear Brake hose slightly deteriorated (3.6.B.4d) Advice Offside Rear Lower Suspension arm has slight play in a ball joint (2.4.G.2) Nearside Front Brake hose slightly deteriorated (3.6.B.4d) Advice Advice Nearside Rear Brake hose slightly deteriorated (3.6.B.4d) Advice Nearside Rear Lower Suspension arm has slight play in a ball joint (2.4.G.2)

CarCheck.co.uk page 5/14



MOT #9 2017-08-22 13:07

MOT test number 335874332963

Result X Failed

Advice Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

**Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail** Exhaust has a major leak of exhaust gases front section with flexi (7.1.2)

**Fail** Nearside Front Front position lamp(s) incorrect colour (1.1.A.3e)

**Advice** Offside Rear Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**Advice** Body has slight corrosion (6.1.B.2)

Advice Offside Front Brake hose slightly deteriorated (3.6.B.4d)

**Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Nearside Rear Lower Suspension arm has slight play in a ball joint (2.4.G.2)

**Fail** Offside Front Front position lamp(s) incorrect colour (1.1.A.3e)

MOT #8 2016-08-18 08:17

**MOT test number** 881398702947

**Result** ✓ Passed

Advice X2 front brake pipes mounting points to in wheel arches loose

MOT #7 2015-08-21 10:13

**MOT test number** 268843835234

**Result** 
✓ Passed

CarCheck.co.uk page 6/14



MOT #6 2014-08-21 14:17

MOT test number 899183934277

Result \( \sqrt{Passed} \)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2013-08-23 12:29

MOT test number 576335033216

Result 

Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #4 2012-08-15 11:31

**MOT test number** 576118822295

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2011-09-05 15:24

MOT test number 339018541448

Result 

Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2010-09-03 09:10

**MOT test number** 924756740282

**Result** 
✓ Passed

CarCheck.co.uk page 7/14



MOT test number

Result

Pass with rectification

Offside Headlamp aim too low (1.8)

Pass with rectification

Nearside Headlamp aim too low (1.8)

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



#### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



### Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-09-14
Last registration	2021-06-23
Complete history	See info



Registration #1	2007-09-14	9 mi
Registration #2	2010-09-03	36.832 mi
Registration #3	2011-09-05	46.458 mi
Registration #4	2012-08-15	54.428 mi
Registration #5	2013-08-23	62.872 mi
Registration #6	2014-08-21	74.877 mi
Registration #7	2015-08-21	92.117 mi
Registration #8	2016-08-18	105.704 mi
Registration #9	2017-08-22	114.682 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.700 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 ea

More info >

CarCheck.co.uk page 13/14



# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2003 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Max. allowed weight	2075 kg

## Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0706271611056G

CarCheck.co.uk page 14/14