



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK220 CDI SPORT
Colour	Silver
Year of manufacture	2009
Top speed	137 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	183 g/km
CO2 label	I





Internet history

Entry 1

Date	2022-04-25
Pictures	10
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-06
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	15
Total items failed	5

MOT #16 2023-12-07 14:12**MOT test number** 618711537645**Result** ✓ Passed**Next expiry date** 2024-12-06**Advice** Nearside Front Lower Suspension arm ball joint has slight play foremost (5.3.4 (a) (i))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement foremost (5.3.4 (a) (i))**MOT #15** 2022-11-30 15:36**MOT test number** 931500937946**Result** ✓ Passed**MOT #14** 2021-11-29 10:10**MOT test number** 846311069657**Result** ✓ Passed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13** 2020-11-23 11:32**MOT test number** 680113030468**Result** ✓ Passed**Advice** Offside Front Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**MOT #12** 2020-11-23 10:28**MOT test number** 404077584887**Result** ✗ Failed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c))**Fail** Windscreen washer not working (3.5 (a))**Advice** Offside Front Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))**MOT #11** 2019-06-01 09:55**MOT test number** 325780209316**Result** ✓ Passed**Advice** Nsf tyre worn outer sidewall**MOT #10** 2019-06-01 09:55**MOT test number** 287317137773**Result** ✗ Failed**Advice** Nsf tyre worn outer sidewall**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #9** 2018-05-31 11:21**MOT test number** 679587291716**Result** ✓ Passed

**MOT #8** 2017-05-26 10:31**MOT test number** 201734941939**Result** ✓ Passed**MOT #7** 2017-05-25 09:53**MOT test number** 451562785331**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin 95%worn (3.5.1g)**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Nearside Rear Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #6** 2016-05-26 10:52**MOT test number** 138906075579**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2015-06-01 16:00**MOT test number** 249082255186**Result** ✓ Passed**MOT #4** 2015-05-29 10:45**MOT test number** 248109945466**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)



MOT #3	2014-05-30 11:01
MOT test number	949720854101
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #2	2013-06-03 10:16
MOT test number	627124853145
Result	✓ Passed

MOT #1	2012-06-02 08:12
MOT test number	169604652151
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
6 December 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-30
Last registration	2023-12-07
Complete history	See info



Registration #1	2009-03-30	6 mi
Registration #2	2012-06-02	46.517 mi
Registration #3	2013-06-03	59.457 mi
Registration #4	2014-05-30	70.484 mi
Registration #5	2015-05-29	82.132 mi
Registration #6	2015-06-01	82.137 mi
Registration #7	2016-05-26	95.297 mi
Registration #8	2017-05-25	101.670 mi
Registration #9	2017-05-26	101.670 mi
Registration #10	2018-05-25	101.670 mi
Registration #11	2018-05-25	101.670 mi
Registration #12	2018-05-25	101.670 mi
Registration #13	2018-05-25	101.670 mi
Registration #14	2018-05-25	101.670 mi
Registration #15	2018-05-25	101.670 mi
Registration #16	2018-05-25	101.670 mi
Registration #17	2018-05-25	101.670 mi
Registration #18	2018-05-25	101.670 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1595 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	64696630637445