





report date: 2024-03-28

General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Black
Year of manufacture	2007
Top speed	134 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	229 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 сс
Cylinders	6
Fuel type	Diesel
Consumption city	19.3 mpg
Consumption extra urban	34.0 mpg
Consumption combined	26.9 mpg
CO2 emission	279 g/km
CO2 label	М



CarCheck.co.uk page 1/16



report date: 2024-03-28

Internet history


Entry 1

Date 2021-09-22

Pictures 34

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-08-03
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	51
Total items failed	17

MOT #19	2023-08-04 09:55
MOT test number	297149160283
Result	✓ Passed
Next expiry date	2024-08-03

MOT #18	2022-06-28 09:33
MOT test number	690852457239
Result	✓ Passed
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	

CarCheck.co.uk page 3/16



report date: 2024-03-28

536665425079

MOT #17 2022-06-23 11:31

MOT test number 140425297178

Result X Failed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Under tray loose

Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

Advice Central Rear Suspension component pin or bush slightly worn (5.3.4 (a) (i))

Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Oil leak on engine

Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #16 2021-06-15 15:49

Result \rightarrow Passed

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources

(4.7.1 (b) (i))

MOT test number

Minor Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

CarCheck.co.uk page 4/16



MOT #15

SG57CAE

report date: 2024-03-28

2021-06-14 14:18

MOT test number

Result

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Minor Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Fail Service brake efficiency below requirements (1.2.2 (a) (i))

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #14

MOT test number

922554388060

Result

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT test number

897052152539

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT test number
922702091240

Result

Advice Rear Brake pad(s) wearing thin 3mm (3.5.1g)

Advice Oil leak misting on the gearbox sump

Advice Rear Child Seat fitted not allowing full inspection of adult belt Both rear seats

Advice Nearside Rear Tyre worn close to the legal limit 3mm 295/35R21 (4.1.E.1)

MOT #11 2018-02-22 10:13 **MOT** test number 504224742518 × Failed Result **Advice** Rear Brake pad(s) wearing thin 3mm (3.5.1g) **Advice** Oil leak misting on the gearbox sump Fail Nearside Rear Registration plate lamp not working (1.1.C.1d) **Advice** Rear Child Seat fitted not allowing full inspection of adult belt Both rear seats **Advice** Nearside Rear Tyre worn close to the legal limit 3mm 295/35R21 (4.1.E.1) Fail Offside Rear Registration plate lamp not working (1.1.C.1d)

MOT #10	2017-02-20 12:58
MOT test number	103830095629
Result	✓ Passed
Advice Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	

CarCheck.co.uk page 6/16



report date: 2024-03-28

MOT #9		2016-02-18 14:47
MOT test	number	194965284165
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Centre Rear nearside seat has child seat fitted not allowing full inspection of sea	at belt
Advice	Nearside Rear seat has child seat fitted not allowing full inspection of seat belt	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Seat belt buckle casing broken and partly missing.	
Advice	Nearside Rear seat has child seat fitted not allowing full inspection of seat belt	

MOT #8	2016-02-18 13:25
MOT test number	850836807203
Result	★ Failed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Centre Rear nearside seat has child seat fitted not allowing full inspection of se	eat belt
Advice Nearside Rear seat has child seat fitted not allowing full inspection of seat belt	
Fail Front registration plate character(s) incorrectly spaced (6.3.4a)	
Fail Front registration plate character(s) sloping (6.3.4b)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Rear Seat belt buckle casing broken and partly missing.	
Advice Nearside Rear seat has child seat fitted not allowing full inspection of seat belt	
Fail Offside Registration plate lamp not fitted (1.1.C.1b)	
Fail Rear registration plate character(s) incorrectly spaced (6.3.4a)	
Fail Rear registration plate character(s) sloping (6.3.4b)	

CarCheck.co.uk page 7/16



report date: 2024-03-28

MOT test number

Fesult

Notice Child seat fitted not allowing full inspection of adult belt

Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT test number
787618644001

Result

Rear registration plate character(s) incorrectly spaced (6.3.4a)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Front registration plate character(s) incorrectly spaced (6.3.4a)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #4	2013-02-08 09:25
MOT test number	547519733099
Result	✓ Passed

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #3		2012-09-19 16:35
MOT test	number	395613462465
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine fault light on	
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #2	2011-06-25 09:17
MOT test number	788546471101
Result	✓ Passed
MOT #1	2010-08-24 11:05
MOT test number	241966030223
Result	✓ Passed

CarCheck.co.uk page 9/16



SG57CAE report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	3 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 10/16




report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



Owner history

SG57CAE

report date: 2024-03-28

C Wile Miscory
For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have?
Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

mber of plates

Plate since

See in this check if this AUDI had different number plates.

ZIS UK

UK UK

More info >

CarCheck.co.uk page 13/16



report date: 2024-03-28

Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-01
Last registration	2023-08-04
Complete history	See info



Registration #1	2007-09-01	13 mi
Registration #2	2010-08-24	31.850 mi
Registration #3	2011-06-25	38.194 mi
Registration #4	2012-09-19	60.858 mi
Registration #5	2013-02-08	66.207 mi
Registration #6	2014-02-17	74.098 mi
Registration #7	2014-02-17	74.098 mi
Registration #8	2015-02-16	81.552 mi
Registration #9	2016-02-18	91.135 mi
Registration #10	2016-02-18	91.135 mi
Registration #11	2017-02-20	102.002 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.117 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 esi
Registration #20		11.777 es
Registration #21		71.777 es

More info >

CarCheck.co.uk page 15/16



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg

Additional information

Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 16/16