



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	B-CLASS B180 CDI SE
Colour	Blue
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	11.8 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-10
Pictures	13
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history****MOT #19** 2021-01-22 14:53**MOT test number** 250130201211**Result** ✓ Passed**Next expiry date** 2022-01-22**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #18** 2020-01-13 11:58**MOT test number** 777415409787**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))**MOT #17** 2019-01-23 09:39**MOT test number** 869242015906**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #16** 2018-01-03 14:18**MOT test number** 383550650588**Result** ✓ Passed**MOT #15** 2018-01-03 14:18**MOT test number** 360860140064**Result** ✗ Failed**Pass with rectification** Nearside Drive shaft which forms part of the suspension coupling gaiter insecure to the extent that it no longer prevents the ingress of dirt etc inner and outer (2.4.G.4e)

**MOT #14** 2017-06-26 14:32**MOT test number** 200486702324**Result** ✓ Passed**Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)**MOT #13** 2017-06-26 13:26**MOT test number** 325972698999**Result** ✗ Failed**Pass with rectification** Nearside Inner Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)**Pass with rectification** Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Rear Wheel stud(s) missing (4.2.A.1e)**Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)**MOT #12** 2016-06-08 15:00**MOT test number** 479188897836**Result** ✓ Passed**MOT #11** 2016-06-08 15:00**MOT test number** 195030776846**Result** ✗ Failed**Pass with rectification** Offside Rear fog lamp not working (1.3.2b)

**MOT #10** 2015-06-24 10:53**MOT test number** 589085275188**Result** ✓ Passed**MOT #9** 2014-05-16 10:41**MOT test number** 527156434146**Result** ✓ Passed**Notice** The fuel filler pipe is rusty.**MOT #8** 2013-05-22 13:23**MOT test number** 869992343111**Result** ✓ Passed**Notice** Slight buckle on n/s/f wheel**MOT #7** 2013-05-21 11:53**MOT test number** 722020962349**Result** ✗ Failed**Notice** Slight buckle on n/s/f wheel**Fail** Nearside Rear coil spring incomplete (2.4.C.1a)**MOT #6** 2012-05-24 12:39**MOT test number** 547515142134**Result** ✓ Passed**MOT #5** 2011-07-14 08:47**MOT test number** 879825491135**Result** ✓ Passed**Notice** 1.All four tyres have cuts on outer walls. 2.Both front brake discs are lipped.**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #4** 2011-07-14 08:47**MOT test number** 507055291130**Result** ✗ Failed**Notice** 1.All four tyres have cuts on outer walls. 2.Both front brake discs are lipped.**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2010-08-03 08:51**MOT test number** 390325210450**Result** ✓ Passed**MOT #2** 2009-08-04 14:56**MOT test number** 370256619263**Result** ✓ Passed**Notice** 1.All four tyres have cuts on outer walls.**MOT #1** 2009-08-04 14:56**MOT test number** 734756519216**Result** ✗ Failed**Pass with rectification** Rear Direction indicators incorrect colour (1.4.A.2f)**Notice** 1.All four tyres have cuts on outer walls.



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 <b>LN55POV</b>
Plate since	2019-03-29
Current registration	 <b>LN55POV</b>
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-09-22
Last registration	2021-01-22
Complete history	<a href="#">See info</a>



Registration #1	2005-09-22	6 mi
Registration #2	2009-08-04	23.800 mi
Registration #3	2010-08-03	27.998 mi
Registration #4	2011-07-14	32.738 mi
Registration #5	2012-05-24	38.685 mi
Registration #6	2013-05-21	45.002 mi
Registration #7	2013-05-22	45.010 mi
Registration #8	2014-05-16	48.974 mi
Registration #9	2015-06-24	53.558 mi
Registration #10	2016-06-08	68.514 mi
Registration #11	2016-06-08	68.514 mi
Registration #12	2016-06-08	68.514 mi
Registration #13	2016-06-08	68.514 mi
Registration #14	2016-06-08	68.514 mi
Registration #15	2016-06-08	68.514 mi
Registration #16	2016-06-08	68.514 mi
Registration #17	2016-06-08	68.514 mi
Registration #18	2016-06-08	68.514 mi
Registration #19	2016-06-08	68.514 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094030112966