



YN580HH

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T32 LWB PBV 102TDI E4
Colour	Black
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	18.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 2.000 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	39.8 mpg
Consumption combined	34.4 mpg





Internet history

Entry 1

Date	2021-05-26
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-08
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	54
Total items failed	4

MOT #18	2023-12-04 12:19
MOT test number	912666479789
Result	✓ Passed
Next expiry date	2024-12-08

MOT #17	2022-12-09 09:54
MOT test number	307450847631
Result	✓ Passed
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16**

2021-11-22 10:11

MOT test number

877090403763

Result

✓ Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Child Seat fitted not allowing full inspection of adult belt

Minor

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor

Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15

2021-01-07 13:01

MOT test number

246269251573

Result

✓ Passed

Advice

Nearside Front Brake caliper anti-rattle spring missing

Advice

Nearside Front Inner Play in steering rack inner joint(s)

Advice

Offside Front Brake caliper anti-rattle spring missing

MOT #14

2021-01-06 15:43

MOT test number

339850302036

Result

✗ Failed

Advice

Nearside Front Inner Play in steering rack inner joint(s)

MAJOR

Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MAJOR

Front Hydraulic fluid leaking excessively Power steering (8.4.1 (a) (i))

Advice

Offside Front Brake caliper anti-rattle spring missing

MAJOR

Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MAJOR

Offside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice

Nearside Front Brake caliper anti-rattle spring missing

**MOT #13** 2020-02-18 12:08**MOT test number** 499382069905**Result** ✓ Passed**MOT #12** 2020-02-17 10:30**MOT test number** 578241249796**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**DANGEROUS** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #11** 2019-03-09 10:37**MOT test number** 447757516705**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #10** 2019-03-08 09:46**MOT test number** 904316278651**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Rear Rear reflector missing (4.8.2 (a) (ii))



MOT #9	2018-02-07 17:31
MOT test number	297129800356
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8	2017-02-20 13:16
MOT test number	203024358445
Result	✓ Passed

MOT #7	2015-11-23 13:13
MOT test number	825900299635
Result	✓ Passed
Advice	Spare wheel missing
Advice	Nearside front tyre sidewall deteriorated
Advice	Items removed from drivers view of the road prior to inspection
Advice	Undertrays fitted obscuring some underside components
Advice	Oil leak
Advice	Offside front tyre sidewall deteriorated
Advice	Small age related cracks in offside rear tyre
Advice	Battery cover fitted obscuring inspection of battery and wiring
Advice	Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
Advice	Exhaust centre silencer slightly corroded

**MOT #6** 2015-11-23 13:13**MOT test number** 726228939619**Result** ✗ Failed

- Advice** Spare wheel missing
- Advice** Nearside front tyre sidewall deteriorated
- Advice** Items removed from drivers view of the road prior to inspection
- Advice** Undertrays fitted obscuring some underside components
- Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Oil leak
- Advice** Offside front tyre sidewall deteriorated
- Advice** Small age related cracks in offside rear tyre
- Advice** Battery cover fitted obscuring inspection of battery and wiring
- Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Exhaust centre silencer slightly corroded

MOT #5 2014-11-26 13:49**MOT test number** 289280434336**Result** ✓ Passed**MOT #4** 2013-11-29 12:48**MOT test number** 296883133313**Result** ✓ Passed

- Notice** Sidewall of rear tyres perished
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Notice** Wipers smearing slightly



MOT #3 2012-11-30 10:18

MOT test number 799455432374

Result ✓ Passed

MOT #2 2012-11-29 13:22

MOT test number 625624432305

Result ✗ Failed

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Stop lamp not working (1.2.1b)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2011-12-12 11:14

MOT test number 676756641389

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
8 December 2024

Tax status		Valid until 1 October
Days left		154
MOT expiry date		8 December 2024
Full MOT history		See MOT history



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YN58OHH
Plate since	2019-06-29
Current registration	 YN58OHH
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-01-23
Last registration	2023-12-04
Complete history	See info



Registration #1	2009-01-23	28 mi
Registration #2	2011-12-12	18.446 mi
Registration #3	2012-11-29	24.475 mi
Registration #4	2012-11-30	24.475 mi
Registration #5	2013-11-29	28.530 mi
Registration #6	2014-11-26	33.656 mi
Registration #7	2015-11-23	38.850 mi
Registration #8	2015-11-23	38.850 mi
Registration #9	2017-02-20	43.743 mi
Registration #10	2018-02-07	55.466 mi
Registration #11	2019-05-29	55.577 mi
Registration #12	2019-05-29	55.577 mi
Registration #13	2019-05-29	55.577 mi
Registration #14	2019-05-29	55.577 mi
Registration #15	2019-05-29	55.577 mi
Registration #16	2019-05-29	55.577 mi
Registration #17	2019-05-29	55.577 mi
Registration #18	2019-05-29	55.577 mi
Registration #19	2019-05-29	55.577 mi
Registration #20	2019-05-29	55.577 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2242 mm
Height	1969 mm
Length	5290 mm
Kerb weight	1849 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	BRS0140892