





report date: 2024-03-29

### General information

Make	MINI
Model	COOPER D R60 COOPER D
Colour	Blue
Year of manufacture	2010
Top speed	112 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history

### Entry 1

Date 2021-08-29

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



WF60NBX
report date: 2024-03-29

MOT history

MOT expiry date	2024-10-20
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	7
Total items failed	2

MOT #13		2023-10-19 15:32
MOT test	number	574945822448
Result		<b>✓</b> Passed
Next expiry date 2024-10-20		
Advice Front Registration plate deteriorated but not likely to be misread Starting to delaminate (0.1 (b))		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing Perished 2014 tyre, ***Strongly Advise Replacement*** 205/55/17 (5.2.3 (d) (ii))		

MOT #12	2022-10-17 08:33
MOT test number	644389745811
Result	<b>✓</b> Passed

MOT #11	2021-10-13 08:26
MOT test number	584505036125
Result	<b>✓</b> Passed

MOT #10	2020-10-10 11:47
MOT test number	934358591984
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9		2020-10-10 09:32
MOT test	number	662374654317
Result		<b>×</b> Failed
MAJOR	Windscreen washer not working (3.5 (a))	
MAIOR	Offside Front Direction indicator incorrect colour (4.4.3 (a))	

	2019-10-21 12:02
number	128672506357
	✓ Passed
Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
	Offside Front Brake disc worn, pitted or scored, but not seriously weakened

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
MOT #7		2018-10-08 13:04
MOT test n	number	554288624006
Result		✓ Passed
MOT #6		2017-09-08 16:04
MOT test n	number	630546448268
Result		✓ Passed
MOT #5		2016-10-18 08:51
MOT test n	number	514649142411
Result		✓ Passed
MOT #4		2015-10-06 09:21
MOT test n	number	101477349754
Result		<b>✓</b> Passed

CarCheck.co.uk page 4/12



**Pass with rectification** 

WF60NBX report date: 2024-03-29

MOT #3 2014-10-07 12:03 **MOT test number** 987240084299 Result ✓ Passed 2013-10-16 10:19 MOT #2 **MOT test number** 276809083265 Result ✓ Passed MOT #1 2013-10-16 10:19 **MOT test number** 326329683286 Result × Failed **Pass with rectification** Nearside Headlamp aim too high (1.8)

Offside Headlamp aim too high (1.8)

CarCheck.co.uk page 5/12



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	20 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



ober of plates

funda scincos

WF60NBX

report date: 2024-03-29

# Owner history For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MINI had different number plates.

m.n.n

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-10-30
Last registration	2023-10-19
Complete history	See info



Registration #1	2010-10-30	17 mi
Registration #2	2013-10-16	11.137 mi
Registration #3	2014-10-07	13.840 mi
Registration #4	2015-10-06	16.034 mi
Registration #5	2016-10-18	20.822 mi
Registration #6	2017-09-08	25.435 mi
Registration #7	2018-10-08	33.429 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		D.777 es
Registration #13		91.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



Car features

WF60NBX

report date: 2024-03-29

60225	Air conditionin
60295	
60482	
0501	
0566	
0567	
60569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	1789 mm
Height	1577 mm
Length	4097 mm
Max. allowed weight	1820 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	72617589

CarCheck.co.uk page 12/12