



 **MK53DSO**

report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA DESIRE 2 PICASSO
Colour	Grey
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	135 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg





Internet history

Entry 1

Date	2021-08-02
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #22	2022-07-25 10:29
MOT test number	576003482566
Result	✓ Passed
Next expiry date	2023-07-31

MOT #21	2021-07-30 08:49
MOT test number	995181000991
Result	✓ Passed

MOT #20	2021-07-28 16:09
MOT test number	747934944874
Result	✗ Failed

- Fail** Registration plate missing (0.1 (a))
- Fail** Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Fail** Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced cill (7.1.1 (a) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #19	2021-07-19 09:08
MOT test number	736720821255
Result	✗ Failed

- Advice** Under body corrosion
- Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))
- Advice** Nearside Front Nail in tyre
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

**MOT #18**

2020-07-20 08:47

MOT test number

570073840345

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Under body corrosion
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Spare tyre defective
- Advice** Front wiper poor
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #17

2019-08-01 11:47

MOT test number

906930362608

Result

✓ Passed

- Advice** Rear exhaust corroded
- Advice** Under body corrosion
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear axle corroded
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #16**

2019-07-24 14:49

MOT test number

478600517309

Result**✗ Failed**

- Advice** Rear axle corroded
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge both edges smooth (5.2.3 (e))
- Fail** Nearside Rear Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear exhaust corroded
- Advice** Under body corrosion
- Advice** Offside Front Tyre worn close to legal limit/worn on edge both edges smooth (5.2.3 (e))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15

2018-07-03 14:59

MOT test number

569001187270

Result**✓ Passed**

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #14**

2018-06-30 10:31

MOT test number

245643132385

Result**✗ Failed**

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Fail** Nearside Front Upper Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Brake pipe excessively corroded main pipe (1.1.11 (c))

MOT #13

2017-06-26 14:39

MOT test number

166482455722

Result**✓ Passed**

- Advice** Central Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)
- Advice** Nearside Seat belt anchorage prescribed area is corroded but not considered excessive outer sill (5.2.6)
- Advice** Front tyres cracking on outer edges

**MOT #12**

2017-06-24 09:27

MOT test number

183083464681

Result

✗ Failed

Fail

Windscreen washer provides insufficient washer liquid (8.2.3)

Advice

Central Rear Brake pipe slightly corroded (3.6.B.2c)

Advice

Offside Rear Brake hose slightly deteriorated (3.6.B.4d)

Advice

Front tyres cracking on outer edges

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail

Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Advice

Nearside Rear Brake hose slightly deteriorated (3.6.B.4d)

Advice

Nearside Seat belt anchorage prescribed area is corroded but not considered excessive outer sill (5.2.6)

MOT #11

2016-07-02 11:10

MOT test number

261858923008

Result

✓ Passed

Advice

Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice

Nearside Front worn on outer edge and cracking

Advice

Nearside Brake pipe slightly corroded center to rear (3.6.B.2c)

MOT #10

2015-07-03 09:35

MOT test number

499374385178

Result

✓ Passed

Advice

Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**MOT #9** 2014-06-28 11:59**MOT test number** 508899574144**Result** ✓ Passed**Notice** Front tyres worn on edges**MOT #8** 2013-06-22 10:34**MOT test number** 689763473159**Result** ✓ Passed**Notice** Nearside wing repettor cover damaged**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #7** 2012-06-18 09:09**MOT test number** 826690572186**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Centre Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2011-07-02 10:30**MOT test number** 689543281127**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Centre Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2010-07-10 08:59**MOT test number** 742101090147**Result** ✓ Passed

**MOT #4** 2009-08-01 11:23**MOT test number** 412713419244**Result** ✓ Passed**Notice** Rear number plate fading**MOT #3** 2008-08-09 10:35**MOT test number** 313622628281**Result** ✓ Passed**MOT #2** 2007-08-18 11:58**MOT test number** 320820937202**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2006-08-26 12:21**MOT test number** 680808636298**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-09-19
Last registration	2022-07-25
Complete history	See info



Registration #1	2003-09-19	18 mi
Registration #2	2006-08-26	20.843 mi
Registration #3	2007-08-18	20.943 mi
Registration #4	2008-08-09	35.146 mi
Registration #5	2009-08-01	42.551 mi
Registration #6	2010-07-10	50.112 mi
Registration #7	2011-07-02	58.252 mi
Registration #8	2012-06-18	68.161 mi
Registration #9	2013-06-22	75.225 mi
Registration #10	2014-06-28	85.020 mi
Registration #11	2015-07-03	92.601 mi
Registration #12	2016-07-02	92.991 mi
Registration #13	2016-07-02	92.991 mi
Registration #14	2016-07-02	92.991 mi
Registration #15	2016-07-02	92.991 mi
Registration #16	2016-07-02	92.991 mi
Registration #17	2016-07-02	92.991 mi
Registration #18	2016-07-02	92.991 mi
Registration #19	2016-07-02	92.991 mi
Registration #20	2016-07-02	92.991 mi
Registration #21	2016-07-02	92.991 mi
Registration #22	2016-07-02	92.991 mi
Registration #23	2016-07-02	92.991 mi
Registration #24	2016-07-02	92.991 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	FX4C1972979