





report date: 2024-03-28

### General information

| Make                | TOYOTA         |
|---------------------|----------------|
| Model               | VERSO D-4D TR  |
| Colour              | Grey           |
| Year of manufacture | 2012           |
| Top speed           | 115 mph        |
| 0 - 60 mph          | 11.3 seconds   |
| Gearbox             | 6 speed Manual |

### Engine & fuel consumption

| Power                   | 125 BHP             |
|-------------------------|---------------------|
| Max. torque             | 310 Nm at 1.800 rpm |
| Engine capacity         | 1.998 сс            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 44.1 mpg            |
| Consumption extra urban | 61.4 mpg            |
| Consumption combined    | 53.3 mpg            |
| CO2 emission            | 139 g/km            |
| CO2 label               | E                   |



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

| _ |   | 4 |    | 7 |
|---|---|---|----|---|
| ᆮ | n | Т | rν | 1 |

| Liid y I      |             |
|---------------|-------------|
| Date          | 2021-10-28  |
| Pictures      | 0           |
| Listing price | View report |

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

### **MOT** history

| MOT expiry date    | 2024-11-26 |
|--------------------|------------|
| MOT pass rate      | 82 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 2          |
| Total advice items | 19         |
| Total items failed | 7          |

| MOT #11   |  | 2023-11-27 11:11 |
|-----------|--|------------------|
| MOT test  | number   | 523850530948     |
| Result    |  | ✓ Passed         |
| Next expi | ry date  | 2024-11-26       |
| Advice    | Central Exhaust mounting defective (6.1.2 (a))                                 |                  |
| Advice    | Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 | (c))             |
| Advice    | Front Direction indicator slightly discoloured both (4.4.3 (a))                |                  |
| Advice    | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) | (ii))            |
| Advice    | Nearside Front Brake pipe corroded, covered in grease or other material (1.1.1 | 1 (c))           |
| Advice    | Offside Front Shock absorbers has light misting of oil (5.3.2 (b))             |                  |

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #10** 2023-11-23 10:33 **MOT** test number 455890875670 Result × Failed **Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b)) Fail Nearside Rear Service brake excessively binding (1.2.1 (f)) Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Central Exhaust mounting defective (6.1.2 (a)) Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Front Direction indicator slightly discoloured both (4.4.3 (a)) Advice Fail Parking brake efficiency below requirements (1.4.2 (a) (i)) Fail Offside Rear Service brake excessively binding (1.2.1 (f)) Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

| MOT #9   | 20  | 022-11-25 12:06 |
|----------|---|-----------------|
| MOT test | number  | 699877319902    |
| Result   |   | ✓ Passed        |
| Advice   | Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) |                 |

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #8 2022-11-24 10:34
MOT test number 344287112574

Result × Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Horn not working (7.7 (a))

MOT #7 2021-11-01 09:40

**MOT test number** 226252751093

**Result** ✓ Passed

MOT #6 2020-10-28 10:04

**MOT test number** 186875121175

**Result** ✓ Passed

**Advice** Nearside Rear Brake cable damaged but not to excess advise n/s/r hand brake intermittently sticking causing bind (1.1.15 (a))

**MOT #5** 2019-04-26 10:46

MOT test number 817521128540

Result \( \sqrt{Passed} \)

MOT #4 2018-05-21 12:22

**MOT test number** 631511050495

**Result** 
✓ Passed

**MOT #3** 2017-05-17 12:04

**MOT test number** 791915131313

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2

MOT test number

Result

Advice Nearside Front tyre cut on outer sidewall

2016-05-16 11:25

229868121630

✓ Passed

MOT #1

MOT test number

958255145156

Result

Notice Both rear tyres wearing low

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 6/13



report date: 2024-03-28

### Tax & MOT check



| Tax status       | Valid until 1 May |
|------------------|-------------------|
| Days left        | 1                 |
| MOT expiry date  | 26 November 2024  |
| Full MOT history | See MOT history   |

### Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | Е          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 7/13



report date: 2024-03-28

### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

| Owner | history |
|-------|---------|
|-------|---------|

| For how long did the current and previous owner(s) have this TOYOTA? How many owne have? Check it in the premium report and see all owner registrations. Download the full |             |
|--|-------------|
|  |             |
|  |             |
| ***************************************  |             |
| ***************************************  |             |
|  |             |
| ***************************************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this TOYOTA had different number plates.  |             |
| Number of plates   |             |
| Current registration   | UK NK       |
| Plate since  |             |
| Current registration   | NK SIE      |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 10/13



report date: 2024-03-28

### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 13         |
| First mileage registration | 2012-05-24 |
| Last registration          | 2023-11-27 |
| Complete history           | See info   |



| Registration #1  | 2012-05-24 | 13 mi      |
|------------------|------------|------------|
| Registration #2  | 2015-05-25 | 37.542 mi  |
| Registration #3  | 2016-05-16 | 48.966 mi  |
| Registration #4  | 2017-05-17 | 64.851 mi  |
| Registration #5  | 2018-05-21 | 81.186 mi  |
| Registration #6  | 2019-04-26 | 91.245 mi  |
| Registration #7  | 2020-10-28 | 111.895 mi |
| Registration #8  |            | 11.777 es  |
| Registration #9  |            | 11.777 es  |
| Registration #10 |            | 11.777 es  |
| Registration #11 |            | 11.777 es  |
| Registration #12 |            | 11.777 es  |
| Registration #13 |            | 10.777 es  |

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| 50501 |                  |
| 50566 |                  |
| 50567 |                  |
| 50569 |                  |

## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 89%             |
| Children       | 75%             |
| Pedestrian     | 69%             |
| Safety systems | 86%             |
| Overall rating | 82%             |
| Video          | see crash video |



## Dimensions & weight

| Width               | 1790 mm |
|---------------------|---------|
| Height              | 1620 mm |
| Length              | 4440 mm |
| Wheel base          | 2780 mm |
| Kerb weight         | 1625 kg |
| Max. allowed weight | 2260 kg |

## Additional information

| Fuel tank capacity                | 55 I             |            |
|-----------------------------------|------------------|------------|
| Fuel delivery                     | Direct Injection |            |
| Number of doors                   | 5                |            |
| Number of seats<br>CarCheck.co.uk | 7                | page 13/13 |

Number of axles 2

**Engine number** 1AD5658782