



report date: 2024-03-28

General information

Make	MINI
Model	COOPER SD
Colour	Black
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 2.700 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 2



Date	2021-10-03
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-10-01
Pictures	16
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2024-11-01
<b>MOT pass rate</b>	67 %
<b>MOT passed</b>	10
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	27
<b>Total items failed</b>	6

**MOT #15** 2023-11-02 14:13**MOT test number** 892551447340**Result** ✓ Passed**Next expiry date** 2024-11-01

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor** Front Windscreen damaged but not adversely affecting driver's view Chipped (3.2 (a) (i))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14** 2023-10-24 15:39**MOT test number** 458313136321**Result** ✗ Failed

**Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

**Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement bush unit is worn not excessively (5.3.4 (a) (i))

**MAJOR** Nearside Front Headlamp aim too high (4.1.2 (a))

**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush unit (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges of the tyre are excessively worn 2 mil can be measured across the treads (5.2.3 (e))

**MAJOR** Front Windscreen wiper does not clear the windscreen effectively both blades are dragging (3.4 (b) (ii))

**MOT #13** 2022-10-25 15:12**MOT test number** 358518632230**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged worn on edges (5.2.3 (d) (ii))**Minor** Windscreen seriously discoloured but not adversely affecting driver's view chipped (3.2 (a) (i))**MOT #12** 2022-10-25 14:32**MOT test number** 494166476038**Result** ✗ Failed**Minor** Windscreen seriously discoloured but not adversely affecting driver's view chipped (3.2 (a) (i))**MAJOR** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))**Advice** Nearside Front Tyre slightly damaged worn on edges (5.2.3 (d) (ii))**MOT #11** 2021-10-02 11:28**MOT test number** 446513682779**Result** ✓ Passed**MOT #10** 2020-10-22 10:13**MOT test number** 103989600921**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2020-10-22 10:13**MOT test number** 683355777111**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-04-25 10:52**MOT test number** 681712192360**Result** ✓ Passed**Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #7** 2018-04-26 09:42**MOT test number** 303114936987**Result** ✓ Passed**Advice** Nearside Non obligatory mirror damaged**Advice** Nearside Front tyre damaged on outer sidewall**MOT #6** 2017-04-26 10:31**MOT test number** 222087848579**Result** ✓ Passed**Advice** Both front tyres have damage to sidewalls just within acceptable limits

**MOT #5** 2017-04-26 10:31**MOT test number** 472636112703**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Both front tyres have damage to sidewalls just within acceptable limits**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #4** 2016-04-26 10:22**MOT test number** 437243909863**Result** ✓ Passed**MOT #3** 2015-04-27 14:22**MOT test number** 388217215177**Result** ✓ Passed**MOT #2** 2014-05-01 15:29**MOT test number** 979941224142**Result** ✓ Passed**Notice** Damage to nearside mirror**MOT #1** 2014-05-01 15:29**MOT test number** 476011824115**Result** ✗ Failed**Notice** Damage to nearside mirror**Pass with rectification** Nearside Headlamp aim too low (1.8)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
1 November 2024

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	155
<b>MOT expiry date</b>	1 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-04-25
Last registration	2023-11-02
Complete history	<a href="#">See info</a>



Registration #1	2011-04-25	20 mi
Registration #2	2014-05-01	6.409 mi
Registration #3	2015-04-27	7.287 mi
Registration #4	2016-04-26	8.209 mi
Registration #5	2017-04-26	8.981 mi
Registration #6	2017-04-26	8.981 mi
Registration #7	2018-04-26	9.719 mi
Registration #8	2019-04-25	10.511 mi
Registration #9	2020-10-22	11.207 mi
Registration #10	2020-10-22	11.207 mi
Registration #11	2020-10-22	11.207 mi
Registration #12	2020-10-22	11.207 mi
Registration #13	2020-10-22	11.207 mi
Registration #14	2020-10-22	11.207 mi
Registration #15	2020-10-22	11.207 mi
Registration #16	2020-10-22	11.207 mi
Registration #17	2020-10-22	11.207 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1150 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number	71667897
---------------	----------