





report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA DESIRE 2 PICASSO
Colour	Blue
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	135 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.2 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date	2021-09-21	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

(i))

MOT test number

122469306658

Result

Next expiry date

Advice

Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #22 2021-11-23 16:57

MOT test number 530812660164

Result × Failed Fail Nearside Obligatory mirror missing (3.3 (a)) Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c)) Fail Nearside Side repeater incorrect colour (4.4.3 (a)) **Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Nearside Front Direction indicator incorrect colour (4.4.3 (a)) **Fail** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice Advice** Coolant leak no coolant tank cap. Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Offside Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b)) Offside Front Position lamp not working (4.2.1 (a) (ii)) Fail **Advice** Low coolant level. **Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) Fail Offside Side repeater incorrect colour (4.4.3 (a)) Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Dipswitch operation does not deflect all main beam headlamps to make them dipped beams (4.1.3 (b)) Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Fail **Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b)) Fail

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #21 2020-10-15 12:55

MOT test number 570402311843

Result \rightarrow Passed

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20 2019-10-18 09:41

MOT test number 918291483034

Result ✓ Passed

MOT #19 2019-10-07 12:16

MOT test number 327911136081

Result X Failed

Fail Nearside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Fail Nearside Front Headlamp light intensity severely reduced (4.1.4 (a))

Fail Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Fail Offside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

Fail Offside Front Headlamp light intensity severely reduced (4.1.4 (a))

MOT #18 2018-10-01 13:14

MOT test number 221071399091

Result
✓ Passed

MOT #17 2017-09-13 15:37

MOT test number 719985808001

CarCheck.co.uk page 5/14



MOT #16 2017-09-13 15:37

MOT test number 505334834175

Result X Failed

Pass with rectification

Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

MOT #15 2016-09-20 11:09

MOT test number 712692380567

Result
✓ Passed

MOT #14 2016-09-20 11:09

MOT test number 676838130293

Result X Failed

Pass with rectification Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #13 2015-09-09 14:56

MOT test number 860242576943

Result
✓ Passed

MOT #12 2014-10-09 14:58

MOT test number 109302884210

Result \(\sqrt{Passed} \)

Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

MOT #11 2013-10-05 09:30

MOT test number 278478973214

Result
✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

 MOT #10
 2013-10-05 09:30

 MOT test number
 335578673429

 Result
 X Failed

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

MOT #9 2012-09-29 08:26

MOT test number 176313572229

Result ✓ Passed

MOT #8 2012-09-22 12:56

MOT test number 366716562464

Result X Failed

Fail Offside Front Track rod end ball joint has excessive play (2.2.B.1f)

Fail Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

MOT #7 2011-10-05 09:15
MOT test number 826558071202
Result ✓ Passed

MOT #6 2011-09-29 10:55

MOT test number 796702671256

Result X Failed

Fail Offside Front Front position lamp(s) not working (1.1.A.3b)

Fail Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)

Fail Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

CarCheck.co.uk page 7/14



MOT #5

GU04ZLV

report date: 2024-03-29

2010-04-30 14:01

MOT test number 272900420457

MOT #4 2010-04-30 14:01

MOT test number 670090720199

Result × Failed

Pass with rectification Offside Front Front constant velocity joint gaiter split (2.5.C.1a)

Pass with rectification Rear Registration plate lamp not working (1.1.C.1d)

Pass with rectification Rear Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #3 2009-05-02 09:15

MOT test number 183792029191

Result \sqrt{Passed}

MOT #2 2008-04-29 11:12

MOT test number 260070428490

Result ✓ Passed

MOT #1 2007-04-19 09:35

MOT test number 693909907143

Result

Passed

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

,		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		OEN

	More info	
	More into	
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-03-01
Last registration	2021-11-27
Complete history	See info



Registration #1	2004-03-01	10 mi
Registration #2	2007-04-19	46.371 mi
Registration #3	2008-04-29	52.034 mi
Registration #4	2009-05-02	57.454 mi
Registration #5	2010-04-30	63.814 mi
Registration #6	2011-09-29	76.027 mi
Registration #7	2011-10-05	76.056 mi
Registration #8	2012-09-22	79.275 mi
Registration #9	2012-09-29	79.285 mi
Registration #10	2013-10-05	82.973 mi
Registration #11	2014-10-09	86.614 mi
Registration #11	2014-10-09	
Registration #12	2015-09-09	97.346 mi
Registration #12	2015-09-09	
Registration #12 Registration #13	2015-09-09	
Registration #12 Registration #13 Registration #14	2015-09-09	
Registration #12 Registration #13 Registration #14 Registration #15	2015-09-09	
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2015-09-09	
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17	2015-09-09	
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18	2015-09-09	
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19	2015-09-09	
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20	2015-09-09	

More info >

CarCheck.co.uk page 13/14



Safety ratings

NCAP rating

Video <u>see crash video</u>

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	FX4T2143295

CarCheck.co.uk page 14/14