



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D S
Colour	Blue
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	9.1 seconds
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	153 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-06-27
Pictures	9
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-05-17
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	14
Total items failed	5

MOT #14	2023-05-18 11:44
MOT test number	510446521987
Result	✓ Passed
Next expiry date	2024-05-17

MOT #13	2022-06-25 16:02
MOT test number	914896122312
Result	✓ Passed

MOT #12	2021-06-29 16:44
MOT test number	748977357010
Result	✓ Passed

Advice Nsf osf coil spring corroded

Advice Oil leak under car front

Advice Osr tyre get close to limit

MOT #11	2020-08-21 09:29
MOT test number	955101151901
Result	✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge outer tread (5.2.3 (e))

**MOT #10**

2020-08-20 13:19

MOT test number

234007417103

Result

✗ Failed

Fail Nearside Front Suspension arm pin or bush excessively worn back bush (5.3.4 (a) (i))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge outer tread (5.2.3 (e))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps both lamps (4.7.1 (b) (ii))**Fail** Offside Front Suspension arm pin or bush excessively worn back bush (5.3.4 (a) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9**

2019-08-10 15:14

MOT test number

453225825329

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8**

2018-07-18 12:01

MOT test number

561278102084

Result

✓ Passed

MOT #7

2017-08-31 08:06

MOT test number

246947348698

Result

✓ Passed

**MOT #6** 2017-08-31 08:06**MOT test number** 104791254270**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #5** 2016-12-20 14:04**MOT test number** 408836161243**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner face (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin n/s/r 3mm - o/s/r 4mm (3.5.1g)**Advice** Vehicles internal headlight adjuster altered to recheck lights**MOT #4** 2016-01-05 12:38**MOT test number** 991775362441**Result** ✓ Passed**MOT #3** 2015-01-09 10:14**MOT test number** 899729105066**Result** ✓ Passed**MOT #2** 2013-12-17 10:47**MOT test number** 248501653314**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2013-01-11 09:20**MOT test number** 477301313092**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
17 May 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	17 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YX10UZT
Plate since	2019-03-28
Current registration	YX10UZT
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-03
Last registration	2023-05-18
Complete history	See info



Registration #1	2010-03-03	18 mi
Registration #2	2013-01-11	18.914 mi
Registration #3	2013-12-17	24.486 mi
Registration #4	2015-01-09	37.880 mi
Registration #5	2016-01-05	52.280 mi
Registration #6	2016-12-20	62.361 mi
Registration #7	2017-08-31	65.887 mi
Registration #8	2017-08-31	65.887 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1446 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number	727050
---------------	--------