



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D DRIVE SE LUX
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-07-18
Pictures	13
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-22
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	51
Total items failed	3

MOT #17	2023-07-21 11:47
MOT test number	669432525244
Result	✓ Passed
Next expiry date	2024-07-22

MOT #16	2022-07-14 16:10
MOT test number	418393184119
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear tyre feathered inner edge
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15	2022-07-14 08:26
MOT test number	282272550205
Result	✗ Failed
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Offside Rear tyre feathered inner edge
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14** 2021-06-25 13:11**MOT test number** 947544651128**Result** ✓ Passed**MOT #13** 2021-05-11 10:25**MOT test number** 142360044246**Result** ✗ Failed**MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #12** 2020-07-23 08:45**MOT test number** 325577217760**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2020-07-22 13:53**MOT test number** 150707298069**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))**MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))



MOT #102019-07-19 11:06

MOT test number412990310331

Result

✓ Passed

- Advice

Front engine injectors leaking combustion gases
- Minor

Front Windscreen wiper blade defective both wipers smear screen (3.4 (b) (i))
- Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Coolant level below min mark
- Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush perishing (5.3.4 (a) (i))



MOT #9 2019-07-12 09:21

MOT test number 555921986235

Result ✗ Failed

MAJOR Nearside Rear Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Rear Brake disc worn, but not excessively both rear disc's hot spots on inner face (1.1.14 (a) (i))

Advice Brake fluid close to minimum mark (1.1.10 (d) (ii))

MAJOR Nearside Front Lower Suspension arm ball joint excessively worn wish bone ball joint worn (5.3.4 (a) (i))

Advice Coolant level below min mark

DANGEROUS Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure sidewall (5.2.3 (d) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush perishing (5.3.4 (a) (i))

MAJOR Offside Rear Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Minor Front Windscreen wiper blade defective both wipers smear screen (3.4 (b) (i))

MAJOR Rear Fluid leak harmful to the environment or a risk to other road users fuel additive tank pump leaking (8.4.1 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush perishing (5.3.4 (a) (i))

Advice Front engine injectors leaking combustion gases

MOT #8 2018-07-06 11:40

MOT test number 715247375360

Result ✓ Passed



MOT #7	2018-07-06 09:01
MOT test number	281474475453
Result	✗ Failed
Advice	O/s/r tyre worn on inner edge
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm and cords exposed (5.2.3 (e))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6	2017-07-14 14:05
MOT test number	496567530478
Result	✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Rear tyres stepping inner shoulder
Advice	Front Brake pad(s) wearing thin 2mm (3.5.1g)
Advice	Rear registration plate faded but not likely to be misread (6.3.1d)
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Exhaust/fume smell in engine bay
Advice	Offside Front Tyre worn close to the legal limit 2mm and bald inner edge (4.1.E.1)

**MOT #5** 2017-07-14 14:05**MOT test number** 240165643489**Result** ✗ Failed**Advice** Rear tyres stepping inner shoulder**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Front Brake pad(s) wearing thin 2mm (3.5.1g)**Advice** Rear registration plate faded but not likely to be misread (6.3.1d)**Advice** Exhaust/fume smell in engine bay**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Tyre worn close to the legal limit 2mm and bald inner edge (4.1.E.1)**MOT #4** 2016-07-25 12:16**MOT test number** 485373392569**Result** ✓ Passed**MOT #3** 2015-07-17 12:27**MOT test number** 817898895144**Result** ✓ Passed**MOT #2** 2014-07-07 11:44**MOT test number** 778938784115**Result** ✓ Passed**MOT #1** 2013-07-12 10:31**MOT test number** 286923893154**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
19 March 2024

✓

MOT

Expires:
22 July 2024

Tax status	Expired at 19 March 2024
Days left	41 days too late
MOT expiry date	22 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-07-28
Last registration	2023-07-21
Complete history	See info



Registration #1	2010-07-28	16 mi
Registration #2	2013-07-12	30.189 mi
Registration #3	2014-07-07	38.911 mi
Registration #4	2015-07-17	47.608 mi
Registration #5	2016-07-25	58.039 mi
Registration #6	2017-07-14	73.314 mi
Registration #7	2017-07-14	73.314 mi
Registration #8	2018-07-06	85.714 mi
Registration #9	2018-07-06	85.714 mi
Registration #10	2019-07-12	98.125 mi
Registration #11	2019-07-12	98.125 mi
Registration #12	2019-07-12	98.125 mi
Registration #13	2019-07-12	98.125 mi
Registration #14	2019-07-12	98.125 mi
Registration #15	2019-07-12	98.125 mi
Registration #16	2019-07-12	98.125 mi
Registration #17	2019-07-12	98.125 mi
Registration #18	2019-07-12	98.125 mi
Registration #19	2019-07-12	98.125 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1260602