





report date: 2024-03-29

#### General information

Make	ТОУОТА
Model	HILUX HL2 SWB 4X4 D-4D CRC
Colour	Green
Year of manufacture	2007
Top speed	96 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	118 BHP
Max. torque	325 Nm at 2.000 rpm
Engine capacity	2.494 сс
Cylinders	4
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	39.2 mpg
Consumption combined	34.0 mpg



CarCheck.co.uk page 1/14



report date: 2024-03-29

# Internet history

#### Entry 1

Date 2021-10-20

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-02-25
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	20
Total items failed	9

MOT #22	2024-02-26 16:45
MOT test number	413742274165
Result	<b>✓</b> Passed
Next expiry date	2025-02-25

MOT #21	2024-01-22 15:35
MOT test	number 594391135893
Result	<b>★</b> Failed
MAJOR	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
MAJOR	Nearside Rear Leaf spring anchor bracket corroded and seriously weakened (5.3.1 (b) (i))
MAJOR (ii))	Offside Rear Rear fog lamp lens defective such that emitted light is adversely affected (4.5.1 (b)

MOT #20	2024	-01-05 13:37
MOT test	number 50	2813815353
Result		<b>X</b> Failed
MAJOR	Nearside Rear Leaf spring fractured (5.3.1 (b) (i))	
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
MAJOR	Offside Rear fog lamp does not emit a steady red light INCORRECT COLOUR (4.5.4 (a))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

**MOT #19** 2023-01-11 08:20

**MOT test number** 780387896888

MOT #18 2022-12-09 09:28

**MOT test number** 773814483788

**Result** X Failed

**MAJOR** Offside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))

**DANGEROUS** Stop lamp(s) all not working (4.3.1 (a) (iii))

**MAJOR** Fuel tank insecure (6.1.3 (a) (i))

**MOT #17** 2021-11-03 09:02

**MOT test number** 571704918927

**Result** ✓ Passed

**MOT #16** 2021-03-31 12:45

MOT test number 934802314802

Result \rightarrow Passed

Advice Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Advice** Front Power steering pipe/hose has slight seepage (2.1.5 (a))

MOT #15 2020-02-20 09:23

MOT test number 398000417202

**Result** ✓ Passed

**MOT #14** 2019-03-01 08:59

**MOT test number** 399975356808

**Result** ✓ Passed

CarCheck.co.uk page 4/14



MOT #7

Result

**MOT** test number

Pass with rectification

**PX56GVF** 

report date: 2024-03-29

2013-12-10 09:01

308324343307

× Failed

MOT #13		2018-02-19 13:51
MOT test number		304807154804
Result		✓ Passed
MOT #12		2017-01-09 09:28
MOT test number		498590845439
Result		✓ Passed
MOT #11		2017-01-09 09:28
MOT test number		811168713840
Result		<b>X</b> Failed
Pass with rectification	Offside Headlamp aim too high (1.8)	
Pass with rectification	Nearside Headlamp aim too high (1.8)	
MOT #10		2016-01-12 11:08
MOT test number		971605696483
Result		✓ Passed
MOT #9		2015-01-06 13:52
MOT test number		835406405049
Result		✓ Passed
MOT #8		2013-12-10 09:01
MOT test number		779284243356
Result		✓ Passed

CarCheck.co.uk page 5/14

Windscreen washer provides insufficient washer liquid (8.2.3)



report date: 2024-03-29

MOT #6 2012-12-18 09:42 **MOT test number** 487193852355 Result ✓ Passed MOT #5 2011-12-09 14:29 **MOT test number** 647673441396 Result ✓ Passed **Notice** Front tyre sidewalls perished **Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d) Notice Offside rear brake tight to rotate Notice Offside front sidewall cut

MOT #4		2010-12-16 14:00
MOT test	number	511100550378
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 6/14



report date: 2024-03-29

2010-12-14 12:09 **MOT** #3 570728240393 **MOT test number** Result × Failed **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Offside Front Seat belt affected by an insecure seat fixing (5.2.1b) Fail Notice Near side front seat missing - no seat belt clip fitted Fail Nearside Registration plate lamp not working (1.1.C.1d) **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) Fail Offside Headlamp not working on dipped beam (1.7.5a) Nearside Headlamp aim too high (1.8) Fail

MOT #2	2010-01-25 14:18
MOT test number	161685820025
Result	./ Passed

MOT #1	2010-01-25 12:53
MOT test number	920475120006
Result	<b>×</b> Failed
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail Brake pedal anti-slip provision missing (3.3.A.1b)	

CarCheck.co.uk page 7/14



PX56GVF report date: 2024-03-29

Tax & MOT check



CarCheck.co.uk page 8/14



report date: 2024-03-29

#### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



PX56GVF report date: 2024-03-29

Owner history

e when miscory		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.		TA
THE PARTY OF THE P		
***************************************		
*********		
***************************************		
	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



report date: 2024-03-29

#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-01-31
Last registration	2024-02-26
Complete history	See info



Registration #1	2007-01-31	17 mi
Registration #2	2010-01-25	22.867 mi
Registration #3	2010-01-25	22.867 mi
Registration #4	2010-12-14	29.439 mi
Registration #5	2010-12-16	29.443 mi
Registration #6	2011-12-09	36.833 mi
Registration #7	2012-12-18	42.536 mi
Registration #8	2013-12-10	46.465 mi
Registration #9	2015-01-06	49.837 mi
Registration #10	2016-01-12	52.490 mi
Registration #11	2017-01-09	55.780 mi
Registration #12	2017-01-09	55.780 mi
		0.777-44
Registration #13		
Registration #14		11.777 es
		11.777 es
Registration #14		11.777 ea 11.777 ea 11.777 ea
Registration #14 Registration #15		11.777 ea 11.777 ea 11.777 ea
Registration #14 Registration #15 Registration #16		11.777 es 11.777 es 11.777 es 11.777 es
Registration #14 Registration #15 Registration #16 Registration #17		11 777 46 11 777 46 11 777 46 11 777 46 11 777 46
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		11 .777 ea 21 .777 ea 21 .777 ea 21 .777 ea 21 .777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11.777 es 11.777 es 11.777 es 11.777 es 11.777 es 11.777 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea 11.777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11 177 46 11 177 46 11 177 46 11 177 46 11 177 46 11 177 46 11 177 46

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

#### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	1760 mm
Height	1795 mm
Length	5255 mm
Kerb weight	1805 kg
Max. allowed weight	2875 kg

### Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	2KD7220361

CarCheck.co.uk page 14/14