



report date: 2024-03-29

General information

Make	HONDA
Model	FR-V I-CTDI EX
Colour	Silver
Year of manufacture	2008
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.204 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H








Internet history

Entry 1

Date	2021-10-26
Pictures	43
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-21
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	20
Total items failed	8

MOT #19	2023-06-19 10:18
MOT test number	118703729930
Result	✓ Passed
Next expiry date	2024-06-21

MOT #18	2022-06-13 14:23
MOT test number	165727683652
Result	✓ Passed
Advice	Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17	2022-06-13 08:38
MOT test number	817880425083
Result	✗ Failed
Fail	Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))
Advice	Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #16** 2021-06-10 13:14**MOT test number** 408649839052**Result** ✓ Passed**Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))**Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**MOT #15** 2021-06-09 10:18**MOT test number** 960725087873**Result** ✗ Failed**Fail** Nearside Front Service brake excessively binding (1.2.1 (f))**Advice** Front Brake pad(s) wearing thin 90% worn (1.1.13 (a) (ii))**MOT #14** 2020-06-22 12:11**MOT test number** 883893950014**Result** ✓ Passed**MOT #13** 2019-04-01 13:37**MOT test number** 508898178567**Result** ✓ Passed**Advice** Slight oil leak from engine area**Advice** Rear wiper split**Advice** Body has damage but secure at time of test**Advice** Both front wiperds poor to clear screen**MOT #12** 2018-04-09 11:03**MOT test number** 757212646842**Result** ✓ Passed

**MOT #11** 2018-04-05 12:36**MOT test number** 180037701771**Result** ✗ Failed**Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)**MOT #10** 2017-04-03 11:23**MOT test number** 476495484474**Result** ✓ Passed**Advice** Wipers smearing**MOT #9** 2017-03-31 15:15**MOT test number** 619534238612**Result** ✗ Failed**Advice** Wipers smearing**Fail** Offside Front Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #8** 2016-03-21 16:48**MOT test number** 472585098279**Result** ✓ Passed

**MOT #7** 2016-03-18 13:48**MOT test number** 370733464269**Result** ✗ Failed**Advice** Nearside Front Tyre has slight damage on sidewall**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**MOT #6** 2015-03-25 09:58**MOT test number** 188564285067**Result** ✓ Passed**MOT #5** 2014-03-27 09:56**MOT test number** 459706184060**Result** ✓ Passed**Notice** Nearside front tyre cut on outer sidewall. no ply exposed**MOT #4** 2013-03-12 18:35**MOT test number** 668451373094**Result** ✓ Passed**MOT #3** 2013-03-12 12:56**MOT test number** 415561073088**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



MOT #2	2012-03-15 10:03
MOT test number	479945172024
Result	✓ Passed
MOT #1	2011-03-22 12:00
MOT test number	745991881008
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
21 June 2024

Tax status	Valid until 1 December
Days left	216
MOT expiry date	21 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	LR08WSV
Plate since	2019-03-29
Current registration	LR08WSV
Plate since	2019-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-29
Last registration	2023-06-19
Complete history	See info



Registration #1	2008-03-29	22 mi
Registration #2	2011-03-22	29.665 mi
Registration #3	2012-03-15	40.892 mi
Registration #4	2013-03-12	51.821 mi
Registration #5	2013-03-12	51.821 mi
Registration #6	2014-03-27	55.653 mi
Registration #7	2015-03-25	63.307 mi
Registration #8	2016-03-18	70.382 mi
Registration #9	2016-03-21	70.382 mi
Registration #10	2017-03-31	77.059 mi
Registration #11	2017-04-03	77.059 mi
Registration #12	2018-03-29	85.337 mi
Registration #13	2018-03-29	85.337 mi
Registration #14	2018-03-29	85.337 mi
Registration #15	2018-03-29	85.337 mi
Registration #16	2018-03-29	85.337 mi
Registration #17	2018-03-29	85.337 mi
Registration #18	2018-03-29	85.337 mi
Registration #19	2018-03-29	85.337 mi
Registration #20	2018-03-29	85.337 mi
Registration #21	2018-03-29	85.337 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1625 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1584 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	N22A13501803