



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 350
Colour	Black
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	5.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	350 Nm at 5.000 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.9 mpg
Consumption extra urban	36.2 mpg
Consumption combined	28.0 mpg
CO2 emission	242 g/km
CO2 label	L






Internet history

Entry 2

Date	2022-02-23
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-10-08
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-13
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	26
Total items failed	3

MOT #19	2024-03-14 12:47
MOT test number	379169014161
Result	✓ Passed
Next expiry date	2025-03-13
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18	2023-03-10 12:43
MOT test number	555204004014
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17** 2023-03-10 12:43**MOT test number** 707238976373**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #16** 2022-02-28 14:56**MOT test number** 779466531136**Result** ✓ Passed**MOT #15** 2022-02-28 10:11**MOT test number** 336733252138**Result** ✗ Failed**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #14** 2020-10-15 13:06**MOT test number** 446648560348**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge both (5.2.3 (e))**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

**MOT #13** 2019-11-18 14:03**MOT test number** 184073003802**Result** ✓ Passed**MOT #12** 2019-11-13 11:34**MOT test number** 645364941468**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Offside Front Brake pipe excessively corroded to rear (1.1.11 (c))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Front Brake pipe excessively corroded to rear (1.1.11 (c))**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MOT #11** 2018-09-27 14:01**MOT test number** 665784028767**Result** ✓ Passed**MOT #10** 2018-09-26 10:13**MOT test number** 653924422508**Result** ✗ Failed**MAJOR** Offside Front Lower Suspension arm ball joint excessively worn Rear (5.3.4 (a) (i))**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #9** 2017-08-22 09:57**MOT test number** 570794267193**Result** ✓ Passed

**MOT #8** 2015-10-06 09:35**MOT test number** 980082036303**Result** ✓ Passed**MOT #7** 2014-10-04 10:29**MOT test number** 668757574216**Result** ✓ Passed**MOT #6** 2013-09-26 09:39**MOT test number** 727629363292**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-08-23 13:52**MOT test number** 655416932252**Result** ✓ Passed**MOT #4** 2012-03-14 16:34**MOT test number** 568554972014**Result** ✓ Passed**MOT #3** 2012-03-14 15:18**MOT test number** 595154072064**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #2** 2011-03-03 09:55**MOT test number** 797302861056**Result** ✓ Passed



MOT #1	2010-03-11 17:08
MOT test number	253330270065
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
13 March 2025

Tax status	Valid until 1 May
Days left	368
MOT expiry date	13 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-03-07
Last registration	2024-03-14
Complete history	See info



Registration #1	2007-03-07	24 mi
Registration #2	2010-03-11	14.540 mi
Registration #3	2011-03-03	18.848 mi
Registration #4	2012-03-14	23.486 mi
Registration #5	2012-03-14	23.486 mi
Registration #6	2012-08-23	25.381 mi
Registration #7	2013-09-26	30.081 mi
Registration #8	2014-10-04	33.446 mi
Registration #9	2015-10-06	37.576 mi
Registration #10	2017-08-22	46.562 mi
Registration #11	2018-09-26	51.340 mi
Registration #12	2019-09-26	55.117 mi
Registration #13	2020-09-26	58.894 mi
Registration #14	2021-09-26	62.671 mi
Registration #15	2022-09-26	66.448 mi
Registration #16	2023-09-26	70.225 mi
Registration #17	2024-03-14	74.002 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		
Registration #22		

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1485 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27296330596135