



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SE SPORT
Colour	White
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	174 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-07-28
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-16
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	37
Total items failed	1

MOT #19 2023-09-22 11:51

MOT test number 943226312570

Result ✓ Passed

Next expiry date 2024-10-16

Advice Nearside Front Tyre slightly damaged outer side wall (5.2.3 (d) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

MOT #18 2023-09-21 15:05

MOT test number 946041856979

Result ✗ Failed

Advice Nearside Front Tyre slightly damaged outer side wall (5.2.3 (d) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

DANGEROUS Offside Rear Shock absorbers likely to become detached (5.3.2 (a) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear bush (5.3.4 (a) (i))

**MOT #17**

2022-10-17 08:27

MOT test number

208775422117

Result

✓ Passed

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Rear subframe is corroded

Advice Both trailing bushes are perished no movemovent

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Both trailing arm bushes are corroded

MOT #16

2021-12-20 14:16

MOT test number

229753639071

Result

✓ Passed

Advice Rear seats down at time of test

Advice General under body corrosion

MOT #15

2020-12-24 10:20

MOT test number

410678532400

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both on inner face (1.1.14 (a) (ii))

**MOT #14** 2019-12-17 12:08**MOT test number** 560553656715**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Suspension components and mountings corroded**MOT #13** 2019-12-16 16:07**MOT test number** 520460712270**Result** ✗ Failed**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Suspension components and mountings corroded**MOT #12** 2018-12-07 09:59**MOT test number** 852932702390**Result** ✓ Passed**MOT #11** 2018-12-05 10:06**MOT test number** 676922347884**Result** ✗ Failed**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** EXHAUST HEAT SHIELD INSECURE**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #10** 2017-12-13 11:06**MOT test number** 468686918981**Result** ✓ Passed

Advice Offside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Nearside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

MOT #9 2017-12-13 11:06**MOT test number** 805916021606**Result** ✗ Failed

Advice Offside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Nearside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)

MOT #8 2016-12-15 10:15**MOT test number** 823442180727**Result** ✓ Passed

Advice Exhaust has a minor leak of exhaust gases [main silencer] (7.1.2)

Advice Offside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

Advice Nearside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

MOT #7 2015-12-01 10:41**MOT test number** 730683934243**Result** ✓ Passed

Advice Front suspension has slight play in a pin or bush of an lower wishbone inner bearing N/S FRONT (2.5.B.1a)

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Front suspension has slight play in a lower wishbone bearing O/S FRONT (2.5.B.1a)



MOT #6	2014-12-15 11:48
---------------	------------------

MOT test number	619399644384
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2013-12-09 11:54
---------------	------------------

MOT test number	648463243372
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2012-12-17 14:36
---------------	------------------

MOT test number	586782052340
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2011-12-05 09:59
---------------	------------------

MOT test number	127719231351
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2010-12-07 09:54
---------------	------------------

MOT test number	862541740348
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2009-12-07 10:09
---------------	------------------

MOT test number	952861649354
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
16 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	16 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-12-29
Last registration	2023-09-22
Complete history	See info



Registration #1	2006-12-29	18 mi
Registration #2	2009-12-07	13.116 mi
Registration #3	2010-12-07	16.884 mi
Registration #4	2011-12-05	20.821 mi
Registration #5	2012-12-17	24.297 mi
Registration #6	2013-12-09	27.514 mi
Registration #7	2014-12-15	31.412 mi
Registration #8	2015-12-01	33.257 mi
Registration #9	2016-12-15	35.438 mi
Registration #10	2017-12-13	37.448 mi
Registration #11	2017-12-13	37.448 mi
Registration #12	2018-09-22	37.448 mi
Registration #13	2018-09-22	37.448 mi
Registration #14	2018-09-22	37.448 mi
Registration #15	2018-09-22	37.448 mi
Registration #16	2018-09-22	37.448 mi
Registration #17	2018-09-22	37.448 mi
Registration #18	2018-09-22	37.448 mi
Registration #19	2018-09-22	37.448 mi
Registration #20	2018-09-22	37.448 mi
Registration #21	2018-09-22	37.448 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1328 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	69500