





General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	Black
Year of manufacture	2015
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history	
Entry 3	
Date	2021-09-29
Pictures	1
Listing price	View report



source: autoonline.co.uk

Entry 2	
Date	2021-09-24
Pictures	0
Listing price	View report
source: heycar.co.uk	
Entry 1	
	2021-09-22
Entry 1	2021-09-22 1



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-19
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	14
Total items failed	4

MOT #7	2023-10-18 14:41
MOT test number	763215260354
Result	✓ Passed
Next expiry date	2024-10-19
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #6	2022-10-17 14:58
MOT test number	845658030014
Result	✓ Passed

MOT #5	2022-10-17 08:09
MOT test number	555456788795
Result	🗙 Failed
Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)))
Fail Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Brake lever has insufficient reserve travel (1.1.2 (a))	
Fail Offside Rear Service brake excessively binding (1.2.1 (f))	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	14 (a) (ii))





МОТ #4	2021-10-20 10:13
MOT test number	822468785071
Result	🗸 Passed
MOT #3	2020-11-06 12:41
MOT test number	300687262002
Result	Passed
MOT #2	2019-11-28 11:19
MOT test number	942616855707
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Minor Nearside Side repeater lens defective which has no effect on emitted light (4	.4.1 (b) (i))
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))

MOT #1		2018-12-03 11:07
MOT test	number	624404520928
Result		✓ Passed
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		ened (1.1.14 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	



Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 April 2025	Expires: 19 October 2024
Tax status	Valid until 1 April
Days left	338
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E Stand
Date	*
Category	AMP
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
see in this check in this fir on DAI had different humber plates.	
Number of sister	
Carrent registration	
Plate since	100.0.0
Current registration	
Plate since	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-11-30
Last registration	2023-10-18
Complete history	<u>See info</u>



Registration #1	2015-11-30	27 mi
Registration #2	2018-12-03	42.708 mi
Registration #3	2019-11-28	50.558 mi
Registration #4	2020-11-06	57.177 mi
Registration #5		11.777 esi
Registration #6		11.777 est
Registration #7		11.777 esi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.117 esi





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg
Additional information	
Fuel tank capacity	58 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	D4FDFZ369714