





report date: 2024-03-29

## General information

Make	MERCEDES
Model	E E240 ELEGANCE
Colour	Silver
Year of manufacture	2002
Top speed	142 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	177 BHP
Max. torque	240 Nm at 4.500 rpm
Engine capacity	2.597 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.1 mpg
Consumption extra urban	36.2 mpg
Consumption combined	27.4 mpg
CO2 emission	247 g/km
CO2 label	L



CarCheck.co.uk page 1/15




# Internet history


## Entry 1

Date 2021-09-12

Pictures 11

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



# MOT history

MOT expiry date	2022-11-05
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	31
Total items failed	11

MOT #22		2021-11-06 14:36
MOT test	number	609580587385
Result		✓ Passed
Next expi	ry date	2022-11-05
Advice	Offside Front Lower Steering rack has slight free play detected at steering wi	heel (2.3 (a) (i))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #21		2020-10-13 08:23
MOT test	number	158812997099
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	High level brake light not working	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 3/15



MOT test number
987579648759

Result

Minor
Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice
Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Advice
Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice
Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #19** 2019-10-18 09:55 **MOT** test number 929642043524 Result × Failed **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii)) Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Fail Nearside Rear Seat belt flexible stalk stretched or damaged likely to lead to failure under load (7.1.2 (b) (ii))

MOT #18		2018-10-18 09:53
MOT test	number	416294550064
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Nail in tyre	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

CarCheck.co.uk page 4/15



EO52JEU

report date: 2024-03-29

MOT #17	2017-10-09 09:12

**MOT test number** 792881979653

**Result** 
✓ Passed

**MOT #16** 2016-10-17 09:24

**MOT test number** 868576491350

**Result** 
✓ Passed

**MOT #15** 2015-10-22 14:34

**MOT test number** 238353493743

Result \( \sqrt{Passed} \)

**MOT #14** 2015-10-22 11:01

**MOT test number** 112563847573

**Result** X Failed

Fail Nearside Front Suspension arm has excessive play in a pin/bush front bush (2.4.G.2)

**Fail** Offside Front Suspension arm has excessive play in a pin/bush front bush (2.4.G.2)

MOT #13 2014-10-13 10:54

**MOT test number** 256536184217

**Result** ✓ Passed

**MOT #12** 2014-10-10 12:08

MOT test number 317953584474

Result × Failed

**Fail** Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

**MOT #11** 2013-10-02 10:00

**MOT test number** 887725673252

CarCheck.co.uk page 5/15



 MOT #10
 2012-10-04 09:44

 MOT test number
 158828772219

Notice Coolant leak

Advice Nearside Front Upper Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #9 2011-10-04 15:36
MOT test number 529937371235

**MOT #8** 2011-09-27 09:48

**MOT test number** 925090871274

Result X Failed

**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #7 2010-09-15 08:59

MOT test number 340218150233

Result 

Passed

MOT #6 2009-09-24 10:24

MOT test number 344797769284

**Result** ✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/15



**MOT #5** 2008-09-22 09:36

MOT test number 163176168254

**Notice** Slight run out on front discs

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4 2008-09-22 09:36

MOT test number 830116568206

**Result** X Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Notice** Slight run out on front discs

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3 2007-09-28 11:22

MOT test number 334521777401

Result \rightarrow Passed

MOT #2 2007-09-14 10:17

MOT test number 830767357206

Result × Failed

**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 7/15



MOT #1 2006-09-18 12:06

**MOT test number** 660501766274

**Result** ✓ Passed

CarCheck.co.uk page 8/15



# Tax & MOT check



X MOT

Tax expired: 1 May 2022 **Expired:** 5 November 2022

Tax status	Expired at 1 May 2022
Days left	730 days too late
MOT expiry date	5 November 2022
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category
Type

Damage 2

Date
Category

Type



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



## Owner history

Owner mistory	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	
2000000	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
2000000	
***************************************	
	More info >
Plate changes  See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 


More info >

CarCheck.co.uk page 13/15



# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2002-09-19
Last registration	2021-11-06
Complete history	See info



Registration #1	2002-09-19	25 mi
Registration #2	2006-09-18	44.880 mi
Registration #3	2007-09-14	53.046 mi
Registration #4	2007-09-28	53.172 mi
Registration #5	2008-09-22	62.787 mi
Registration #6	2009-09-24	70.543 mi
Registration #7	2010-09-15	80.938 mi
Registration #8	2011-09-27	90.329 mi
Registration #9	2011-10-04	90.334 mi
Registration #10	2012-10-04	99.016 mi
Registration #11	2013-10-02	104.117 mi
Registration #12	2014-10-10	105.324 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		0.77 es
Registration #18		11.777 es
Registration #19		0.77 es
Registration #20		11.777 es
Registration #21		0.0746
Registration #22		11.777 es
Registration #23		10.707 au

More info >

CarCheck.co.uk page 14/15



## Dimensions & weight

Width	1980 mm
Height	1440 mm
Length	4818 mm
Wheel base	2833 mm
Kerb weight	1570 kg

### Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	11291331340358

CarCheck.co.uk page 15/15