





report date: 2024-03-29

#### General information

Make	FIAT
Model	DOBLO 16V SX MULTIJET
Colour	Blue
Year of manufacture	2016
Top speed	98 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.6 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-29

### Internet history

#### Entry 1

Date 2021-10-07

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



BK16THX
report date: 2024-03-29

MOT history

MOT expiry date	2025-02-13
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	13
Total items failed	7

MOT #8		2024-01-29 13:49
MOT test	number	652173046206
Result		✓ Passed
Next expi	ry date	2025-02-13
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Both top strut mounts noisy	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #7	2024-01-26 10:13
MOT test number	571151827171
Result	<b>X</b> Failed
Advice Both top strut mounts noisy	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii	i))
Fail Nearside Front Tyre has a cut in excess of the requirements deep enough (5.2.3 (d) (i))	to reach the ply or cords
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #6	2023-02-14 09:46
MOT test number	266450381108
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

Passed

**MOT #5** 2023-02-09 09:26

**MOT test number** 306506800749

**Result** X Failed

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #4** 2021-05-24 08:44

**MOT test number** 629844211234

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge 2 - 3.2mm remaining wear on inner edge

(5.2.3 (e))

Result

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #3 2020-06-16 09:02

**MOT test number** 381094255364

Result \rightarrow Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2020-06-12 12:29

**MOT test number** 899218380161

Result X Failed

**Fail** Offside Front Suspension arm pin or bush excessively worn Rear (5.3.4 (a) (i))

**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Fuel cap/sealing device ineffective (6.1.3 (b) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn Rear (5.3.4 (a) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2019-04-17 08:21
MOT test number 130963120706

**Result** ✓ Passed

CarCheck.co.uk page 5/12



BK16THX
report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	13 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
***************************************	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	NK 312
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-05-24
Last registration	2024-01-29
Complete history	See info



Registration #1	2016-05-24	9 mi
Registration #2	2019-04-17	24.532 mi
Registration #3	2020-06-12	36.755 mi
Registration #4	2020-06-16	36.761 mi
Registration #5	2021-05-24	44.064 mi
Registration #6		71.777 es
Registration #6 Registration #7		11.777 ea
-		11.777 es 11.777 es
Registration #7		11,777 es 11,777 es 11,777 es

More info >

CarCheck.co.uk page 11/12



BK16THX report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1345 kg
Max. allowed weight	2420 kg

# Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number Carcheck.co.uk	6114278 page 12/12