



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS SPORT TDI
Colour	Grey
Year of manufacture	2007
Top speed	126 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.800 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G







Internet history

Entry 2


Date	2021-08-05
Pictures	23
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-04
Pictures	23
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-06-17
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	20
Total items failed	10

MOT #19 2023-05-30 08:49**MOT test number** 805056680484**Result** ✓ Passed**Next expiry date** 2024-06-17

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge and inner edge also outer sidewall (5.2.3 (e))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #18 2023-05-26 08:55**MOT test number** 706785986741**Result** ✗ Failed

Fail Offside Front Lower Coil spring fractured or broken coil (5.3.1 (b) (i))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge and inner edge also outer sidewall (5.2.3 (e))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #17 2022-05-25 09:42**MOT test number** 956176055361**Result** ✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #16** 2021-06-18 09:51**MOT test number** 909306255298**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged outer sidewall 235/40/18 (5.2.3 (d) (ii))**MOT #15** 2020-06-11 12:31**MOT test number** 514620408916**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii))**Advice** Offside Rear Upper Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #14** 2019-04-06 10:49**MOT test number** 691608922762**Result** ✓ Passed**MOT #13** 2018-04-30 12:40**MOT test number** 820723627096**Result** ✓ Passed**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement Offside front and nearside front, lower arms, rear bushes. (2.4.G.2)**MOT #12** 2017-04-28 11:44**MOT test number** 639750448019**Result** ✓ Passed**Advice** Tyre pressure monitoring system warning lamp illuminated

**MOT #11** 2017-04-28 11:02**MOT test number** 151365794069**Result** ✗ Failed**Advice** Tyre pressure monitoring system warning lamp illuminated**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure 235/40/18 (4.1.D.1b)**Fail** Windscreen wiper does not clear the windscreen effectively both front wipers (8.2.2)**MOT #10** 2016-04-26 14:46**MOT test number** 398201118443**Result** ✓ Passed**MOT #9** 2016-04-26 14:31**MOT test number** 355845133612**Result** ✗ Failed**Advice** Tyre pressure monitoring system light on**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure inner edge distorted 235/40/18 (4.1.D.1b)**MOT #8** 2015-04-24 16:33**MOT test number** 519734315134**Result** ✓ Passed

**MOT #7**

2015-04-24 10:39

MOT test number

485994315110

Result**✗ Failed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Rear brake excessively fluctuating (3.7.B.3)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Front brake excessively fluctuating (3.7.B.3)**MOT #6**

2014-04-28 14:35

MOT test number

147658014121

Result**✓ Passed****Notice** Rear brake discs faces corroded and pad linings low**Notice** N/s/r tyre worn on inside edge**MOT #5**

2013-04-30 15:36

MOT test number

127040923143

Result**✓ Passed****MOT #4**

2013-04-24 14:46

MOT test number

529084813110

Result**✗ Failed****Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2012-04-26 13:42
MOT test number	778137512124
Result	✓ Passed
MOT #2	2011-04-15 14:25
MOT test number	749075201153
Result	✓ Passed
MOT #1	2011-04-15 11:20
MOT test number	195405101194
Result	✗ Failed
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
17 June 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	17 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 FV57KBZ
Plate since	2019-03-29
Current registration	 FV57KBZ
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-11-02
Last registration	2023-05-30
Complete history	See info



Registration #1	2007-11-02	13 mi
Registration #2	2011-04-15	18.198 mi
Registration #3	2011-04-15	18.198 mi
Registration #4	2012-04-26	24.921 mi
Registration #5	2013-04-24	31.750 mi
Registration #6	2013-04-30	31.770 mi
Registration #7	2014-04-28	36.665 mi
Registration #8	2015-04-24	44.200 mi
Registration #9	2015-04-24	44.201 mi
Registration #10	2016-04-26	48.244 mi
Registration #11	2016-04-26	48.244 mi
Registration #12	2016-05-20	51.277 mi
Registration #13	2016-05-20	51.277 mi
Registration #14	2016-05-20	51.277 mi
Registration #15	2016-05-20	51.277 mi
Registration #16	2016-05-20	51.277 mi
Registration #17	2016-05-20	51.277 mi
Registration #18	2016-05-20	51.277 mi
Registration #19	2016-05-20	51.277 mi
Registration #20	2016-05-20	51.277 mi
Registration #21	2016-05-20	51.277 mi
Registration #22	2016-05-20	51.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1570 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Engine number	BMM 122233