



report date: 2024-03-28

General information

Make	KIA
Model	RIO GS
Colour	Silver
Year of manufacture	2006
Top speed	110 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	96 BHP
Max. torque	125 Nm at 4.700 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	150 g/km
CO2 label	F





Internet history

Entry 2

Date	2023-01-12
Pictures	2
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-05-28
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-06
MOT pass rate	70 %
MOT passed	16
Failed MOT tests	7
Total advice items	32
Total items failed	11

MOT #23	2024-02-07 16:29
MOT test number	872456367082
Result	✓ Passed
Next expiry date	2025-02-06

MOT #22	2023-01-17 09:24
MOT test number	669542699961
Result	✓ Passed

MOT #21	2023-01-16 13:01
MOT test number	465193789994
Result	✗ Failed

MAJOR Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Front Position lamp not working (4.2.1 (a) (ii))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #20**

2022-03-22 12:03

MOT test number

954100959644

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #19

2022-03-22 10:23

MOT test number

862580650912

Result

✗ Failed

MAJOR Nearside Front Brake hose excessively stretched on full lock (1.1.12 (b) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #18

2021-02-25 10:43

MOT test number

402636354108

Result

✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened corroded inner face (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2-3mm inner edge (5.2.3 (e))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened corroded inner face (1.1.14 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2-3mm outer edge (5.2.3 (e))

MOT #17

2020-02-28 12:34

MOT test number

950359462212

Result

✓ Passed

**MOT #16** 2019-02-28 10:55**MOT test number** 879947407311**Result** ✓ Passed**MOT #15** 2018-02-16 10:23**MOT test number** 352904282999**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #14** 2017-02-20 09:18**MOT test number** 166510075782**Result** ✓ Passed**MOT #13** 2016-03-02 09:35**MOT test number** 307765206392**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit bang on limit inner edge (4.1.E.1)**Advice** Offside Rear inner face brake disc corroded**MOT #12** 2015-03-04 09:18**MOT test number** 389723265096**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2015-03-04 09:18**MOT test number** 177623565473**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2014-03-07 14:13**MOT test number** 145476364484**Result** ✓ Passed**Notice** O/s/f tyre is wearing inner edge.**MOT #9** 2013-02-22 10:54**MOT test number** 785333953073**Result** ✓ Passed**MOT #8** 2012-02-24 09:27**MOT test number** 976735752067**Result** ✓ Passed**MOT #7** 2012-02-23 13:54**MOT test number** 185904052000**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Fail** Power steering pump leaking from a failed seal (2.3.3b)**Fail** Service brake: efficiency below requirements (3.7.C.1a)**Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Brake performance not tested (3.7.A.1)**MOT #6** 2011-02-24 14:09**MOT test number** 169265151415**Result** ✓ Passed

**MOT #5** 2011-02-24 11:41**MOT test number** 786325651054**Result** ✗ Failed**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Notice** Front discs corroded.**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2010-02-15 12:58**MOT test number** 493416340008**Result** ✓ Passed**Notice** Nearside rear brake readings slightly down.**Notice** Offside and nearside rear brake discs inner faces corroded, recommend attention.**MOT #3** 2010-02-15 12:58**MOT test number** 732766940082**Result** ✗ Failed**Notice** Nearside rear brake readings slightly down.**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Offside and nearside rear brake discs inner faces corroded, recommend attention.**MOT #2** 2009-02-16 12:05**MOT test number** 581537549078**Result** ✓ Passed**Notice** Engine management light on.**Notice** Washer jets need adjustment.**Notice** Front and rear brake discs inner faces corroding/worn.



MOT #12009-02-16 12:05

MOT test number821687749093

Result

Failed

Notice

Washer jets need adjustment.

Notice

Front and rear brake discs inner faces corroding/worn.

Pass with rectification

Nearside Headlamp aim too high (1.8)

Notice

Engine management light on.

Pass with rectification

Offside Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
6 February 2025

Tax status	Valid until 1 August
Days left	95
MOT expiry date	6 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-03-08
Last registration	2024-02-07
Complete history	See info



Registration #1	2006-03-08	20 mi
Registration #2	2009-02-16	17.522 mi
Registration #3	2010-02-15	18.424 mi
Registration #4	2011-02-24	19.287 mi
Registration #5	2011-02-24	19.287 mi
Registration #6	2012-02-23	20.408 mi
Registration #7	2012-02-24	20.408 mi
Registration #8	2013-02-22	21.181 mi
Registration #9	2014-03-07	21.955 mi
Registration #10	2015-03-04	22.638 mi
Registration #11	2016-03-02	23.603 mi
Registration #12	2017-02-20	24.257 mi
Registration #13	2018-02-20	25.000 mi
Registration #14	2019-02-20	25.000 mi
Registration #15	2020-02-20	25.000 mi
Registration #16	2021-02-20	25.000 mi
Registration #17	2022-02-20	25.000 mi
Registration #18	2023-02-20	25.000 mi
Registration #19	2024-02-07	25.000 mi
Registration #20		
Registration #21		
Registration #22		
Registration #23		

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1695 mm
Height	1470 mm
Length	3990 mm
Wheel base	2500 mm
Kerb weight	1079 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4EE6H03319