



AE63FSO

report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 DSTYLE RED
Colour	Black
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.200 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	132 g/km
CO2 label	E





MOT history

MOT expiry date	2024-05-08
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	29
Total items failed	11

MOT #11	2023-05-09 11:12
MOT test number	774210509339
Result	✓ Passed
Next expiry date	2024-05-08
Advice	Offside Front Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #10	2023-05-03 10:17
MOT test number	674523006823
Result	✗ Failed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Advice	Offside Front Inner Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #9** 2022-05-05 10:37**MOT test number** 756183256692**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #8** 2021-04-16 14:00**MOT test number** 870040351385**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2020-09-03 10:09**MOT test number** 965039260136**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2020-09-03 07:50**MOT test number** 741626403195**Result** ✗ Failed**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))

**MOT #5**

2019-09-04 15:04

MOT test number

172305553524

Result

✓ Passed

- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #4

2019-09-04 12:30

MOT test number

434516919062

Result

✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Headlamp aim not tested (4.1.2 (b))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure inner wall (5.2.3 (d) (ii))
- Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords on tread (5.2.3 (d) (i))

MOT #3

2018-08-17 11:00

MOT test number

313849116363

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #2	2017-08-18 10:42
MOT test number	995157361587
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened both worn (3.5.1i)
Advice	Damage to nearside outer sill
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2016-06-30 06:47
MOT test number	723990749552
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
8 May 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	8 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-27
Last registration	2023-05-09
Complete history	See info



Registration #1	2013-09-27	19 mi
Registration #2	2016-06-30	31.618 mi
Registration #3	2017-08-18	42.718 mi
Registration #4	2018-08-17	53.190 mi
Registration #5	2019-09-04	63.951 mi
Registration #6	2019-09-04	63.951 mi
Registration #7	2019-09-04	63.951 mi
Registration #8	2019-09-04	63.951 mi
Registration #9	2019-09-04	63.951 mi
Registration #10	2019-09-04	63.951 mi
Registration #11	2019-09-04	63.951 mi
Registration #12	2019-09-04	63.951 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1715 mm
Height	1483 mm
Length	3948 mm
Wheel base	2464 mm
Kerb weight	1075 kg
Max. allowed weight	1554 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	FHCA1916011