



OUI3LWR

report date: 2024-03-28

General information

Make	JAGUAR
Model	XJ D V6 PREMIUM LUXURY
Colour	Silver
Year of manufacture	2013
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	275 BHP
Max. torque	600 Nm at 2.000 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-08-01
Pictures	15
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-31
Pictures	15
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2025-04-12
<b>MOT pass rate</b>	82 %
<b>MOT passed</b>	9
<b>Failed MOT tests</b>	2
<b>Total advice items</b>	18
<b>Total items failed</b>	5

**MOT #11** 2024-04-09 12:41**MOT test number** 500185611687**Result** ✓ Passed**Next expiry date** 2025-04-12

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10** 2023-04-11 11:23**MOT test number** 673356530035**Result** ✓ Passed

- Advice** Nearside Front Coil spring corroded At base of spring (5.3.1 (b) (i))

**MOT #9** 2022-04-13 11:32**MOT test number** 744603974468**Result** ✓ Passed

- Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

**MOT #8** 2022-03-29 11:19**MOT test number** 600003461116**Result** ✗ Failed**Fail** Suspension arm pin or bush excessively worn both front lower front arms (5.3.4 (a) (i))**Fail** Exhaust emissions exceed manufacturer's specified limit 0.50 (8.2.2.2 (a))**Advice** Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))**Fail** Brake pad(s) worn down to wear indicator both front (1.1.13 (a) (i))**Fail** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))**MOT #7** 2021-03-19 11:44**MOT test number** 650449060590**Result** ✓ Passed**Advice** Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement front arm (5.3.4 (a) (i))**Advice** Oil leak, but not excessive rear diff (8.4.1 (a) (i))**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement front arm (5.3.4 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #6** 2020-03-18 16:26**MOT test number** 761347624907**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm bush deteriorated. (5.3.4 (a) (i))**MOT #5** 2019-03-05 14:52**MOT test number** 882867622803**Result** ✓ Passed

**MOT #4** 2018-03-20 14:42**MOT test number** 247017589212**Result** ✓ Passed**Advice** Nearside Front Suspension arm has slight play in a pin/bush front (2.4.G.2)**Advice** Offside Front Suspension arm has slight play in a pin/bush front (2.4.G.2)**Advice** Rear diff leaking**MOT #3** 2018-03-20 11:12**MOT test number** 947234421451**Result** ✗ Failed**Advice** Rear diff leaking**Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)**Advice** Offside Front Suspension arm has slight play in a pin/bush front (2.4.G.2)**Advice** Nearside Front Suspension arm has slight play in a pin/bush front (2.4.G.2)**MOT #2** 2017-03-13 09:56**MOT test number** 755278027397**Result** ✓ Passed**MOT #1** 2016-03-29 09:16**MOT test number** 394432425321**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
12 April 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	94
<b>MOT expiry date</b>	12 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-03-28
Last registration	2024-04-09
Complete history	<a href="#">See info</a>



Registration #1	2013-03-28	27 mi
Registration #2	2016-03-29	19.925 mi
Registration #3	2017-03-13	26.602 mi
Registration #4	2018-03-20	28.087 mi
Registration #5	2018-03-20	28.087 mi
Registration #6	2019-03-05	37.224 mi
Registration #7	2020-03-18	47.198 mi
Registration #8	2020-03-20	55.277 mi
Registration #9	2020-03-20	55.277 mi
Registration #10	2020-03-20	55.277 mi
Registration #11	2020-03-20	55.277 mi
Registration #12	2020-03-20	55.277 mi
Registration #13	2020-03-20	55.277 mi
Registration #14	2020-03-20	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	62%
Safety systems	71%
Overall rating	74%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1894 mm
Height	1448 mm
Length	5122 mm
Wheel base	3157 mm
Kerb weight	1796 kg
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	82 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	0790777306DT