



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI DSG 140
Colour	Red
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	172 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-09-17
Pictures	31
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-21
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	20
Total items failed	7

MOT #13	2023-09-09 17:57
MOT test number	642474206414
Result	✓ Passed
Next expiry date	2024-09-21
Advice	Nearside Rear Suspension arm corroded but not seriously weakened lower (5.3.3 (b) (i))
Advice	Offside Rear Suspension arm corroded but not seriously weakened lower (5.3.3 (b) (i))
Advice	Fuel tank support straps are slightly corroded but not weakened
Advice	Integral body structure is corroded but structural rigidity is not significantly reduced underneath including all suspension components (6.1.1 (c) (i))

MOT #12	2022-09-14 14:09
MOT test number	956455584779
Result	✓ Passed

**MOT #11**

2022-09-12 16:12

MOT test number

575110447332

Result

✗ Failed

- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Direction indicator not working damaged (4.4.1 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

MOT #10

2021-09-22 15:57

MOT test number

584884531967

Result

✓ Passed

- Advice** Rusty underside due to age

MOT #9

2020-08-24 15:33

MOT test number

651909119498

Result

✓ Passed

- Advice** Front brake pads worn
- Advice** Upper stop lamp not working

MOT #8

2019-09-02 10:02

MOT test number

316729972004

Result

✓ Passed

**MOT #7** 2018-09-10 14:10**MOT test number** 456346694131**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge heavily worn inner edge (5.2.3 (e))**MOT #6** 2017-10-03 14:27**MOT test number** 537496023131**Result** ✓ Passed**MOT #5** 2016-10-03 07:55**MOT test number** 886702193561**Result** ✓ Passed**MOT #4** 2015-09-29 11:32**MOT test number** 405605166791**Result** ✓ Passed**MOT #3** 2014-09-30 14:18**MOT test number** 198323174211**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2013-10-15 09:54
MOT test number	505458183283
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components
Notice	Passenger seat(s) missing at time of test

MOT #1	2012-09-28 11:48
MOT test number	796872772265
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
21 September 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	SL59LFX
Plate since	2019-06-29
Current registration	SL59LFX
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-10-26
Last registration	2023-09-09
Complete history	See info



Registration #1	2009-10-26	18 mi
Registration #2	2012-09-28	21.409 mi
Registration #3	2013-10-15	31.567 mi
Registration #4	2014-09-30	42.226 mi
Registration #5	2015-09-29	53.652 mi
Registration #6	2016-10-03	63.517 mi
Registration #7	2017-10-03	70.325 mi
Registration #8	2018-09-10	80.949 mi
Registration #9	2019-09-10	91.573 mi
Registration #10	2020-09-10	102.197 mi
Registration #11	2021-09-10	112.821 mi
Registration #12	2022-09-10	123.445 mi
Registration #13	2023-09-10	134.069 mi
Registration #14	2024-09-10	144.693 mi
Registration #15	2025-09-10	155.317 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number

BKD C66894