



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 1700 CDTI
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 2.300 rpm
Engine capacity	1.686 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg



LABEL UNKNOWN



MOT history

MOT expiry date	2025-02-20
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	37
Total items failed	19

MOT #21	2024-02-13 15:17
MOT test number	208015934495
Result	✓ Passed
Next expiry date	2025-02-20
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #20** 2024-02-05 14:10**MOT test number** 496005206767**Result** ✗ Failed**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #19** 2023-02-21 15:33**MOT test number** 744216494014**Result** ✓ Passed**MOT #18** 2023-02-17 09:23**MOT test number** 914900136575**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #17** 2022-02-18 16:48**MOT test number** 150521506575**Result** ✓ Passed**MOT #16** 2022-02-18 10:44**MOT test number** 843966018362**Result** ✗ Failed

- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #15 2021-02-13 09:09**MOT test number** 741303987075**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin offside rear inner pad (1.1.13 (a) (ii))

MOT #14 2021-02-13 09:09**MOT test number** 850254984821**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin offside rear inner pad (1.1.13 (a) (ii))
- Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #13**

2020-01-17 15:51

MOT test number

438227197476

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge EDGES (5.2.3 (e))**Advice** WHEEL TRIMS FITTED ALL ROUND**Advice** Nearside Front Tyre worn close to legal limit/worn on edge EDGES (5.2.3 (e))**Advice** REAR EXHAUST BOX VERY RUSTY**MOT #12**

2019-01-07 11:07

MOT test number

956782376894

Result

✓ Passed

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge INNER EDGE (5.2.3 (e))**Advice** WHEEL TRIMS FITTED ALL ROUND**MOT #11**

2018-01-03 11:03

MOT test number

187855112372

Result

✓ Passed

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit INNER EDGE (4.1.E.1)**Advice** Central Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #10** 2018-01-03 11:03**MOT test number** 980631218794**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit INNER EDGE (4.1.E.1)**Advice** Central Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2017-02-01 09:44**MOT test number** 599454079963**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit Wearing on inner tread (4.1.E.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #8** 2017-01-30 11:16**MOT test number** 404578272418**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Headlamp not working on dipped beam AIM NOT TESTED (1.7.5a)**Advice** Nearside Front Tyre worn close to the legal limit Wearing on inner tread (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm Worn on inner tread (4.1.E.1)**MOT #7** 2016-01-06 17:04**MOT test number** 180771842462**Result** ✓ Passed

**MOT #6** 2015-01-12 09:28**MOT test number** 117512115086**Result** ✓ Passed**MOT #5** 2014-01-20 13:04**MOT test number** 206160124073**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #4** 2014-01-20 09:16**MOT test number** 139070624493**Result** ✗ Failed**Fail** Offside Rear fog lamp adversely affected by the operation of another lamp (1.3.2f)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Offside Stop lamp adversely affected by the operation of another lamp (1.2.1f)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-01-14 12:08**MOT test number** 658714413063**Result** ✓ Passed**MOT #2** 2012-01-03 13:33**MOT test number** 178583102049**Result** ✓ Passed



MOT #1	2011-01-18 11:18
MOT test number	117888611098
Result	✓ Passed
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
20 February 2025

Tax status		Valid until 1 October
Days left		154
MOT expiry date		20 February 2025
Full MOT history		See MOT history




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29
Number of owners	1
Current owner since	2019-09-29
Previous owner since	2019-09-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 HD57EEO
Plate since	2019-09-29
Current registration	 HD57EEO
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-01-30
Last registration	2024-02-13
Complete history	See info



Registration #1	2008-01-30	20 mi
Registration #2	2011-01-18	26.225 mi
Registration #3	2012-01-03	32.219 mi
Registration #4	2013-01-14	35.187 mi
Registration #5	2014-01-20	39.604 mi
Registration #6	2014-01-20	39.604 mi
Registration #7	2015-01-12	43.328 mi
Registration #8	2016-01-06	46.575 mi
Registration #9	2017-01-30	56.457 mi
Registration #10	2017-02-01	56.457 mi
Registration #11	2018-01-03	67.563 mi
Registration #12	2019-01-03	67.563 mi
Registration #13	2019-01-03	67.563 mi
Registration #14	2019-01-03	67.563 mi
Registration #15	2019-01-03	67.563 mi
Registration #16	2019-01-03	67.563 mi
Registration #17	2019-01-03	67.563 mi
Registration #18	2019-01-03	67.563 mi
Registration #19	2019-01-03	67.563 mi
Registration #20	2019-01-03	67.563 mi
Registration #21	2019-01-03	67.563 mi
Registration #22	2019-01-03	67.563 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1252 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	1736147