



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	AVENSIS VALVEMATIC TR
Colour	Grey
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	52.3 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-07-07
Pictures	2
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-16
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	60
Total items failed	4

MOT #17	2023-09-16 09:36
MOT test number	859316164744
Result	✓ Passed
Next expiry date	2024-09-16
Advice	Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #16**

2022-09-10 15:28

MOT test number

334387528724

Result

✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #15**

2022-09-10 14:12

MOT test number

245928576871

Result**✗ Failed****MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**MAJOR** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #14**

2021-09-17 08:05

MOT test number

123557163021

Result**✓ Passed**

**MOT #13** 2020-11-23 08:51**MOT test number** 501452819375**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #12** 2020-11-21 11:06**MOT test number** 612738489532**Result** ✗ Failed**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick both sides (1.1.13 (a) (ii))**MAJOR** Emissions not tested (8.2.1.2 (d))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick both sides (1.1.13 (a) (ii))**MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #11** 2019-12-16 14:53**MOT test number** 423055515350**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #10** 2018-12-11 09:07**MOT test number** 204440094029**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Exhaust heat shield loose.**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #9**

2018-12-06 09:08

MOT test number

124515292492

Result**✗ Failed**

- Advice** Exhaust heat shield loose.
- MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))
- MAJOR** Electronic braking system warning device inoperative (1.7 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- MAJOR** Offside Headlamp aim too high and too far to the right. (4.1.2 (a))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a))
- Advice** Items removed from driver's view prior to test
- MAJOR** Nearside Headlamp aim too high and too far to the right. (4.1.2 (a))

MOT #8

2017-12-18 16:48

MOT test number

678827818894

Result**✓ Passed**

- Advice** Nearside Rear Nail in tyre
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened Discs badly worn (3.5.1i)
- Advice** Rear brake application & release uneven
- Advice** Rear exhaust heat shield insecure
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Front Tyre worn close to the legal limit On limit & bald on edges (4.1.E.1)
- Advice** Rear tyres cracking

**MOT #7** 2017-10-25 10:52**MOT test number** 625185246856**Result** ✗ Failed**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Advice** Nearside Front Tyre worn close to the legal limit outer edg (4.1.E.1)**Fail** Electronic parking brake warning indicates a malfunction (3.1.7)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #6** 2016-10-31 16:33**MOT test number** 144604776012**Result** ✓ Passed**MOT #5** 2015-10-31 12:04**MOT test number** 199706119399**Result** ✓ Passed**MOT #4** 2014-10-30 15:57**MOT test number** 746313504359**Result** ✓ Passed**MOT #3** 2013-08-21 11:05**MOT test number** 248093533221**Result** ✓ Passed**MOT #2** 2012-09-11 17:49**MOT test number** 618595452209**Result** ✓ Passed



MOT #1	2012-05-19 11:55
MOT test number	277500642126
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
16 September 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	16 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-05-21
Last registration	2023-09-16
Complete history	See info



Registration #1	2009-05-21	27 mi
Registration #2	2012-05-19	16.570 mi
Registration #3	2012-09-11	18.609 mi
Registration #4	2013-08-21	26.548 mi
Registration #5	2014-10-30	35.246 mi
Registration #6	2015-10-31	48.052 mi
Registration #7	2016-10-31	61.712 mi
Registration #8	2017-10-25	67.056 mi
Registration #9	2017-12-18	67.098 mi
Registration #10	2018-12-06	69.338 mi
Registration #11	2019-05-20	70.377 mi
Registration #12	2019-05-20	70.377 mi
Registration #13	2019-05-20	70.377 mi
Registration #14	2019-05-20	70.377 mi
Registration #15	2019-05-20	70.377 mi
Registration #16	2019-05-20	70.377 mi
Registration #17	2019-05-20	70.377 mi
Registration #18	2019-05-20	70.377 mi
Registration #19	2019-05-20	70.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1480 mm
Length	4695 mm
Wheel base	2700 mm
Kerb weight	1455 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	2ZFU186720