



KV59FFG

report date: 2024-03-29

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 SWB P/V HDI 120
Colour	White
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-06
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-20
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	23
Total items failed	16

MOT #15	2023-10-19 13:42
MOT test number	511267284842
Result	✓ Passed
Next expiry date	2024-10-20
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear TYRE IS DOWN TO 2MM ON INNER & OUTER PART OF TYRE
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2022-10-19 11:24
MOT test number	127638006481
Result	✓ Passed
Advice	Nearside Rear TYRE IS DOWN TO 2MM ON INNER & OUTER PART OF TYRE
Advice	Offside Rear TYRE IS DOWN TO 2MM ON INNER & OUTER PART OF TYRE
Advice	Nearside Front TYRE IS DOWN TO 2MM ON INNER & OUTER PART OF TYRE
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Front TYRE IS DOWN TO 2MM ON OUTER PART OF TYRE

**MOT #13** 2021-10-21 10:29**MOT test number** 671726353859**Result** ✓ Passed**MOT #12** 2021-01-06 12:32**MOT test number** 316601049299**Result** ✓ Passed**MOT #11** 2021-01-05 11:56**MOT test number** 854728052876**Result** ✗ Failed**Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Exhaust mounting defective both rear brackets broken exhaust still supported (6.1.2 (a))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**MOT #10** 2019-11-20 16:39**MOT test number** 630163322455**Result** ✓ Passed

**MOT #9** 2019-11-19 09:29**MOT test number** 117294925495**Result** ✗ Failed**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #8** 2018-02-08 12:32**MOT test number** 442016424058**Result** ✓ Passed**Advice** Nearside Rear handbrake cable cover frayed**MOT #7** 2018-02-05 09:20**MOT test number** 419139015780**Result** ✗ Failed**Fail** Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Nearside Rear handbrake cable cover frayed**Fail** Nearside Front Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #6** 2016-12-16 14:51**MOT test number** 638109612666**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Exhaust bracket broken

**MOT #5** 2016-12-15 11:31**MOT test number** 734775976001**Result** ✗ Failed

Fail Nearside Front Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #4 2015-12-10 12:17**MOT test number** 389297462949**Result** ✓ Passed**MOT #3** 2015-12-09 09:21**MOT test number** 872846844122**Result** ✗ Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Rear tyre perished and in general poor condition

Fail Registration plate lamp not working (1.1.C.1d)

MOT #2 2014-02-19 15:12**MOT test number** 745120854020**Result** ✓ Passed



MOT #1	2013-05-22 14:32
MOT test number	309952343145
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
20 October 2024

Tax status		Valid until 1 November
Days left		187
MOT expiry date		20 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 KV59FFG
Plate since	2019-03-29
Current registration	 KV59FFG
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In kilometers
Mileage registrations	17
First mileage registration	2009-09-10
Last registration	2023-10-19
Complete history	See info



Registration #1	2009-09-10	7 mi
Registration #2	2013-05-22	52.361 mi
Registration #3	2014-02-19	65.177 mi
Registration #4	2015-12-09	86.198 mi
Registration #5	2015-12-10	86.200 mi
Registration #6	2016-12-15	91.675 mi
Registration #7	2016-12-16	91.680 mi
Registration #8	2018-02-05	94.247 mi
Registration #9	2018-02-08	151.917 mi
Registration #10	2019-05-29	151.917 mi
Registration #11	2019-05-29	151.917 mi
Registration #12	2019-05-29	151.917 mi
Registration #13	2019-05-29	151.917 mi
Registration #14	2019-05-29	151.917 mi
Registration #15	2019-05-29	151.917 mi
Registration #16	2019-05-29	151.917 mi
Registration #17	2019-05-29	151.917 mi

More info >



Dimensions & weight

Width	2194 mm
Height	1942 mm
Length	4805 mm
Kerb weight	1714 kg
Max. allowed weight	2702 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	DYXA4011506