



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I20 CLASSIC
Colour	Black
Year of manufacture	2013
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	114 g/km
CO2 label	C







Internet history

Entry 1

Date	2021-06-10
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-14
MOT pass rate	56 %
MOT passed	9
Failed MOT tests	7
Total advice items	22
Total items failed	17

MOT #16	2024-02-15 08:58
MOT test number	455242142263
Result	✓ Passed
Next expiry date	2025-02-14
Advice	Under body painted with under seal

MOT #15	2022-11-07 13:05
MOT test number	688651466286
Result	✓ Passed
Advice	Front Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
Advice	Under body covered in under seal

MOT #14	2022-11-07 13:05
MOT test number	427959251170
Result	✗ Failed
Advice	Under body covered in under seal
Advice	Front Brake pipe corroded, covered in grease or other material both (1.1.11 (c))
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #13** 2022-07-05 10:18**MOT test number** 840296766329**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Sub-frame corroded but not seriously weakened both subframe and underbody corrosion (5.3.3 (b) (i))**MOT #12** 2021-05-12 13:35**MOT test number** 574235887669**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))**MOT #11** 2021-05-12 13:35**MOT test number** 472976147328**Result** ✗ Failed**Pass with rectification** Offside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))**Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))**MOT #10** 2020-03-20 13:34**MOT test number** 914113188093**Result** ✓ Passed**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Offside Front Driver's door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inside edge (5.2.3 (e))

**MOT #9** 2020-03-20 10:09**MOT test number** 770033215150**Result** ✗ Failed**Fail** Nearside Rear Brake pipe excessively corroded Hose to hose (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Inside edge (5.2.3 (e))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Rear Brake pipe excessively corroded Hose to hose (1.1.11 (c))**Minor** Offside Front Driver's door catch deteriorated so the door cannot be readily opened or closed (6.2.3 (c) (i))**MOT #8** 2019-03-16 11:54**MOT test number** 309408340304**Result** ✓ Passed**MOT #7** 2019-03-13 10:25**MOT test number** 555094288831**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Fail** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #6** 2018-03-27 13:47**MOT test number** 436816026936**Result** ✓ Passed

**MOT #5** 2018-03-23 11:45**MOT test number** 395517889250**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside and offside rear tyres very heavy cracking and poor condition**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #4** 2017-03-24 09:31**MOT test number** 714870308116**Result** ✓ Passed**Advice** Nearside Front Nail in tyre**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #3** 2017-03-24 09:31**MOT test number** 532300621482**Result** ✗ Failed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Nail in tyre**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)



MOT #2	2016-03-29 12:23
MOT test number	814721480270
Result	✓ Passed

MOT #1	2016-03-29 12:23
MOT test number	434937033226
Result	✗ Failed

Pass with rectification

 Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
14 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	14 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2013-01-14
Last registration	2024-02-15
Complete history	See info



Registration #1	2013-01-14	20 mi
Registration #2	2016-03-29	26.861 mi
Registration #3	2016-03-29	26.861 mi
Registration #4	2017-03-24	40.185 mi
Registration #5	2017-03-24	40.185 mi
Registration #6	2018-03-23	54.280 mi
Registration #7	2018-03-27	54.527 mi
Registration #8	2019-03-13	68.879 mi
Registration #9	2019-03-16	69.039 mi
Registration #10	2019-03-20	75.377 mi
Registration #11	2019-03-20	75.377 mi
Registration #12	2019-03-20	75.377 mi
Registration #13	2019-03-20	75.377 mi
Registration #14	2019-03-20	75.377 mi
Registration #15	2019-03-20	75.377 mi
Registration #16	2019-03-20	75.377 mi
Registration #17	2019-03-20	75.377 mi
Registration #18	2019-03-20	75.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1083 kg
Max. allowed weight	1515 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	G4LACM940592
---------------	--------------