





report date: 2024-03-29

#### General information

Make	BMW
Model	X1 520D M SPORT GRAN TURISMO
Colour	Black
Year of manufacture	2014
Top speed	133 mph
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	181 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	51.4 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/12



### Internet history

#### Entry 2

Date 2023-09-09

Pictures 49

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-01-29	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-04
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	16
Total items failed	0

MOT #8	2023-09-05 15:12
MOT test number	936508916706
Result	✓ Passed
Next expiry date	2024-09-04

MOT #7		2022-11-18 16:02
MOT test	number	641763761874
Result		✓ Passed
Advice	O/S/R Tyre worn low on tread.	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Nail in tyre	

CarCheck.co.uk page 3/12



**MOT #6** 2022-11-18 12:21

**MOT test number** 958293058447

Result X Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**DANGEROUS** Offside Front Lower Suspension arm modified so the suspension is likely to foul other components Rear most arm (5.3.3 (c) (ii))

Advice Nearside Rear Nail in tyre

**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn Rear most arm bush (5.3.4 (a) (i))

**Advice** O/S/R Tyre worn low on tread.

**DANGEROUS** Nearside Front Suspension arm modified so the suspension is likely to foul other components Rear most arm (5.3.3 (c) (ii))

**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn Rear most arm (5.3.4 (a) (i))

MOT #5 2021-11-30 09:13

**MOT test number** 343892443600

**Result** 
✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner and outer (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge inner and outer (5.2.3 (e))

MOT #4 2020-12-16 09:54

MOT test number 186267712923

Result 

Passed

**MOT #3** 2019-12-16 14:54

**MOT test number** 879964338197

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 225/45/18 (5.2.3 (e))

CarCheck.co.uk page 4/12



YE64AAY

report date: 2024-03-29

MOT #2 2018-10-24 11:05

**MOT test number** 826602485032

**Result** 
✓ Passed

MOT #1 2017-10-24 08:23

**MOT test number** 550619694069

**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)

Advice Offside Rear Outer Rear position lamp(s) has light sources not illuminating, but not more than

50% (1.1.A.3b)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	4 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



YE64AAY

report date: 2024-03-29

#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra BMW salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did Check it in the premium report and see all owner registrations. Download the full report in the premium report and see all owner registrations.		ve?
***************************************		
THE STATE OF THE S		
***************************************		
	More info	>
Plate changes		
See in this check if this BMW had different number plates.		
Number of plates		9
Current registration	OK SIE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-10-30
Last registration	2023-09-05
Complete history	See info



Registration #1	2014-10-30	16 mi
Registration #2	2017-10-24	34.043 mi
Registration #3	2018-10-24	46.600 mi
Registration #4	2019-12-16	60.274 mi
Registration #5	2020-12-16	71.031 mi
Registration #6		11.777 es
Registration #7		11.777 esi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



## Dimensions & weight

Width	1901 mm
Height	1559 mm
Length	5004 mm
Wheel base	3070 mm
Kerb weight	1915 kg
Max. allowed weight	2545 kg

# Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles2Engine number91958852