



FA030HN

report date: 2024-03-29

General information

Make	NISSAN
Model	PRIMERA T-SPEC
Colour	Blue
Year of manufacture	-
Top speed	119 mph
0 - 60 mph	10.9 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	138 BHP
Max. torque	192 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.1 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-29
Pictures	27
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #23	2021-08-17 14:19
MOT test number	196084415642
Result	✓ Passed
Next expiry date	2022-08-28
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Under vehicle slightly corroded
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Brake hose slightly deteriorated all visible (1.1.12 (b) (ii))

MOT #22	2021-08-17 14:19
MOT test number	882882496177
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Front Headlamp lens seriously defective both lens cloudy (4.1.1 (b) (ii))
Advice	Under vehicle slightly corroded
Advice	Brake hose slightly deteriorated all visible (1.1.12 (b) (ii))

MOT #21	2020-08-17 12:57
MOT test number	589254573606
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge heavily worn inner edge (5.2.3 (e))

**MOT #20**

2019-08-14 14:32

MOT test number

982061285801

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake hose slightly deteriorated all visible brake hoses (1.1.12 (b) (ii))
- Advice** Inner sills corroded
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #19

2018-08-02 08:02

MOT test number

789481869442

Result

✓ Passed

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Covers & shield fitted
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #18

2017-08-25 12:15

MOT test number

406249803918

Result

✓ Passed

MOT #17

2017-08-25 07:41

MOT test number

286900097513

Result

✗ Failed

- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Fail** Driver's door cannot be opened from outside the vehicle (6.2.B.1b)
- Fail** Emissions not tested Rear box broken (7.3.A.1)

**MOT #16** 2016-08-05 10:14**MOT test number** 573709938849**Result** ✓ Passed**Advice** Under trays fitted**Advice** OSR tyre worn on inner edge**MOT #15** 2016-08-05 10:14**MOT test number** 749443701829**Result** ✗ Failed**Advice** OSR tyre worn on inner edge**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Under trays fitted**MOT #14** 2015-07-29 15:47**MOT test number** 535980715210**Result** ✓ Passed**Notice** O/s/r tyre wearing on edges

**MOT #13** 2015-07-29 09:07**MOT test number** 189280915290**Result** ✗ Failed**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Notice** O/s/f tyre wearing on edges**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Notice** Engine management light on**MOT #12** 2014-08-27 14:38**MOT test number** 425489434289**Result** ✓ Passed**MOT #11** 2013-08-06 11:29**MOT test number** 325918113290**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**MOT #10** 2012-08-15 13:52**MOT test number** 918288022273**Result** ✓ Passed

**MOT #9** 2012-08-15 11:37**MOT test number** 465818622257**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #8** 2011-08-15 10:00**MOT test number** 255237321277**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2010-08-25 13:10**MOT test number** 751327130209**Result** ✓ Passed**Advice** Nearside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**MOT #6** 2010-08-19 14:44**MOT test number** 740931330224**Result** ✗ Failed**Fail** Power steering component(s) leaking (2.3.3b)**Advice** Nearside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #5** 2009-08-19 12:44**MOT test number** 933511539256**Result** ✓ Passed

**MOT #4** 2008-08-20 10:34**MOT test number** 590223838228**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2007-08-29 16:48**MOT test number** 930321147200**Result** ✓ Passed**MOT #2** 2007-08-29 11:18**MOT test number** 333301647297**Result** ✗ Failed**Notice** Cuts in offside rear tyre sidewalls**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #1** 2006-07-04 14:50**MOT test number** 161505086132**Result** ✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-07-23
Last registration	2021-08-17
Complete history	See info



Registration #1	2003-07-23	24 mi
Registration #2	2006-07-04	13.926 mi
Registration #3	2007-08-29	23.432 mi
Registration #4	2007-08-29	23.434 mi
Registration #5	2008-08-20	31.432 mi
Registration #6	2009-08-19	39.022 mi
Registration #7	2010-08-19	84.378 mi
Registration #8	2010-08-25	45.647 mi
Registration #9	2011-08-15	51.896 mi
Registration #10	2012-08-15	57.514 mi
Registration #11	2012-08-15	57.514 mi
Registration #12	2013-08-06	63.251 mi
Registration #13	2014-08-27	70.893 mi
Registration #14	2015-08-27	70.893 mi
Registration #15	2016-08-27	70.893 mi
Registration #16	2017-08-27	70.893 mi
Registration #17	2018-08-27	70.893 mi
Registration #18	2019-08-27	70.893 mi
Registration #19	2020-08-27	70.893 mi
Registration #20	2021-08-27	70.893 mi
Registration #21	2022-08-27	70.893 mi
Registration #22	2023-08-27	70.893 mi
Registration #23	2024-08-27	70.893 mi
Registration #24	2025-08-27	70.893 mi
Registration #25	2026-08-27	70.893 mi



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1488 mm
Length	4567 mm
Wheel base	2680 mm
Kerb weight	1399 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	032635