



General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Red
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2022-01-23
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-20
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	36
Total items failed	12

MOT #18	2024-01-19 11:13
MOT test number	617958253101
Result	✓ Passed
Next expiry date	2025-01-20
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))

MOT #17	2024-01-19 09:35
MOT test number	688399614130
Result	✗ Failed
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #16	2023-01-12 13:09
MOT test number	851103963660
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Rear Coil spring corroded both rear springs (5.3.1 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15** 2022-01-21 18:33**MOT test number** 136689355769**Result** ✓ Passed**MOT #14** 2022-01-12 13:05**MOT test number** 343196699147**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Front Headlamp not working on main beam (4.1.1 (a) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #13** 2021-04-20 15:25**MOT test number** 956393276822**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #12** 2020-03-10 15:59**MOT test number** 649283625409**Result** ✓ Passed**Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #11**

2019-03-11 17:04

MOT test number

253710226949

Result

✓ Passed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #10

2018-03-28 15:03

MOT test number

628889326484

Result

✓ Passed

- Advice** Both front tyres split and cracked
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Exhaust system corroded
- Advice** Oil leak slight leak sump corroded
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)

**MOT #9** 2018-03-28 11:07**MOT test number** 422850232284**Result** ✗ Failed

- Advice** Oil leak slight leak sump corroded
- Advice** Both front tyres split and cracked
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Exhaust system corroded
- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #8 2017-02-27 10:40**MOT test number** 762193298025**Result** ✓ Passed**MOT #7** 2016-02-29 11:39**MOT test number** 525948074927**Result** ✓ Passed

- Advice** Oil leak on engine

MOT #6 2015-02-17 10:34**MOT test number** 149828345077**Result** ✓ Passed

**MOT #5** 2014-03-05 14:38**MOT test number** 979304964003**Result** ✓ Passed**MOT #4** 2013-02-20 14:35**MOT test number** 178141753401**Result** ✓ Passed**Notice** Both rear coil springs corroded**Notice** Both rear tyres treads cracking**MOT #3** 2013-02-20 12:49**MOT test number** 829861853071**Result** ✗ Failed**Notice** Both rear tyres treads cracking**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Both rear coil springs corroded**MOT #2** 2012-02-08 09:21**MOT test number** 155419232002**Result** ✓ Passed**Notice** Corrosion to exhaust silencer**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Slight cracking to o/s/r tyre tread



MOT #12012-02-07 15:26

MOT test number939948532013

Result		✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Notice	Corrosion to exhaust silencer	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail	Centre Statutory seat belt missing (5.1.1)	
Notice	Slight cracking to o/s/r tyre tread	



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
20 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	20 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXX XX
Plate since	2024-03-29
Current registration	XXXX XX
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-02-24
Last registration	2024-01-19
Complete history	See info



Registration #1	2009-02-24	11 mi
Registration #2	2012-02-07	25.611 mi
Registration #3	2012-02-08	25.611 mi
Registration #4	2013-02-20	34.213 mi
Registration #5	2013-02-20	34.213 mi
Registration #6	2014-03-05	42.692 mi
Registration #7	2015-02-17	50.269 mi
Registration #8	2016-02-29	53.604 mi
Registration #9	2017-02-27	57.841 mi
Registration #10	2018-03-28	61.546 mi
Registration #11	2019-03-29	65.257 mi
Registration #12	2019-03-29	65.257 mi
Registration #13	2019-03-29	65.257 mi
Registration #14	2019-03-29	65.257 mi
Registration #15	2019-03-29	65.257 mi
Registration #16	2019-03-29	65.257 mi
Registration #17	2019-03-29	65.257 mi
Registration #18	2019-03-29	65.257 mi
Registration #19	2019-03-29	65.257 mi
Registration #20	2019-03-29	65.257 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694